



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

March 6, 2017

### Seat-Mounted Air Bags may not Deploy

**NHTSA Campaign Number:** 17V115000

**Manufacturer** BMW of North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 292

#### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2017 430i, 430i xDrive, 440i, 440i xDrive and M4 vehicles and Rolls-Royce Dawn vehicles. The affected vehicles have seat-mounted Autoliv side air bag inflator initiators that may fail to ignite during a crash.

#### **Remedy**

BMW will notify owners, and dealers will replace the air bag modules, free of charge. The recall is expected to begin April 17, 2017. Owners may contact BMW customer service at 1-800-525-7417.

#### **Vehicles**

MAKE	MODEL YEAR	
BMW	430I	2017
BMW	440I	2017
BMW	M4	2017
ROLLS-ROYCE DAWN		2017

## Improperly Sealed Power Steering Connectors

**NHTSA Campaign Number:** 17V116000

**Manufacturer** General Motors LLC

**Components** STEERING

**Potential Number of Units Affected** 2,085

### **Summary**

General Motors LLC (GM) is recalling certain 2017 Buick LaCrosse vehicles. The electrical connectors for the Delphi Electronic Power Steering (EPS) system may not be properly sealed. As a result, water may enter and corrode the connectors possibly resulting in a loss of power steering.

### **Remedy**

GM will notify owners, and dealers will inspect correct the seal seating and secure the EPS connector seals, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Buick customer service at 1-800-521-7300. GM's number for this recall is 17085.

### **Vehicle**

**MAKE MODEL YEAR**

BUICK LACROSSE 2017