



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

April 17, 2017

### Doors may Open Unexpectedly

**NHTSA Campaign Number:** 17V233000

**Manufacturer** Mitsubishi Motors North America, Inc.

**Components** LATCHES/LOCKS/LINKAGES

**Potential Number of Units Affected** 35,674

### Summary

Mitsubishi Motors North America, Inc. (MMNA) is recalling certain 2016 Outlander and Outlander Sport vehicles. The Ansei inside door latch mechanisms may not latch securely in high temperatures, allowing the doors to open while vehicle is in motion.

### Remedy

MMNA will notify owners, and dealers will replace the door latches, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact MMNA customer service at 1-888-648-7820. MMNA's number for this recall is SR-17-002.

### Vehicles

| MAKE       | MODEL           | YEAR |
|------------|-----------------|------|
| MITSUBISHI | OUTLANDER       | 2016 |
| MITSUBISHI | OUTLANDER SPORT | 2016 |

Vehicle may Roll when in Park/FMVSS 102/114

**NHTSA Campaign Number:** 17V225000

**Manufacturer** Ford Motor Company

**Components** POWER TRAIN

**Potential Number of Units Affected** 48,443

**Summary**

Ford Motor Company (Ford) is recalling certain 2017 Ford F-250 Super Duty trucks equipped with 6.2L engines and six-speed automatic transmissions. These transmissions may have a damaged Burkland park rod actuating plate that can result in unexpected vehicle movement even though the transmission has been shifted to 'Park.' As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 102, "Transmission Shift Lever Sequence/Starter Interlock/Transmission Braking Effect", and number 114, "Theft Protection."

**Remedy**

Ford will notify owners, and dealers will inspect the park rod actuating plate and replace it, if necessary, free of charge. Remedy parts are currently unavailable. Interim notices informing owners of the safety risk are expected to be mailed in April 2017. Owners will receive a second notice when remedy parts become available. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17C06.

**Vehicle**

**MAKE MODEL YEAR**

FORD F-250 SD 2017