



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

July 10, 2017

Third Row Center Seat Belt may not Latch/FMVSS 208

NHTSA Campaign Number: 17V397000

Manufacturer Honda (American Honda Motor Co.)

Components SEAT BELTS

Potential Number of Units Affected 3,927

Summary

Honda (American Honda Motor Co.) is recalling certain 2018 Honda Odyssey vehicles. The Autoliv seat belt tongue for the third row center seating position may not be compatible with the latch, preventing the seat belt from latching securely. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

Remedy

Honda will notify owners, and dealers will inspect the third row center seat belt to make sure that it has the correct tongue, replacing the seat belt, if necessary, free of charge. The recall is expected to begin July 24, 2017. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is KF7.

Vehicle

MAKE	MODEL	YEAR
HONDA	ODYSSEY	2018

Incorrect Air Bag Deployment Calibration Settings

NHTSA Campaign Number: 17V394000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 4,926

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2010-2011 XJ vehicles. If, while servicing the vehicle, the vehicle does not successfully receive an update to the Restraint Control Module (RCM) software, the default air bag calibration settings may be incorrect.

Remedy

Jaguar will notify owners, and dealers will update the RCM with the latest software, free of charge. The recall is expected to begin on August 18, 2017. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H034.

Vehicle

MAKE	MODEL	YEAR
JAGUAR	XJ	2010-201

Driver's Knee Air Bag may not Inflate/FMVSS 208

NHTSA Campaign Number: 17V398000

Manufacturer Ford Motor Company

Components AIR BAGS

Potential Number of Units Affected 3

Summary

Ford Motor Company (Ford) is recalling certain 2016 Ford Escape vehicles. The Autoliv driver's knee airbag modules installed in these vehicles were produced without the inflator gas generant material, and, as a result, the air bags may not inflate properly in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

Remedy

Ford will notify owners, and dealers will replace driver's knee air bag, free of charge. The recall is expected to begin August 18, 2017. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 17C11.

Vehicle

MAKE	MODEL	YEAR
FORD	ESCAPE	2016

Crash Avoidance Parking Brake Use/FMVSS 108

NHTSA Campaign Number: 17V400000

Manufacturer Volkswagen Group of America, Inc.

Components EXTERIOR LIGHTING, FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 24,754

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2016-2017 Audi Q3 vehicles. If the parking brake is used during emergency braking, the brake lights on the vehicle will not activate. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

Audi will notify owners, and dealers will update the vehicle software, free of charge. The recall is expected to begin in July 2017. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 45G6.

Vehicle

MAKE	MODEL	YEAR
AUDI	Q3	2016-2017