



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

July 17, 2017

### Inadvertent Air Bag Deployment due to Chafed Wire

**NHTSA Campaign Number:** 17V432000

**Manufacturer** Chrysler (FCA US LLC)

**Components** AIR BAGS

**Potential Number of Units Affected** 363,480

#### **Summary**

Chrysler (FCA US LLC) is recalling certain 2011-2015 Dodge Journey vehicles. In the affected vehicles, the driver's frontal air bag may unexpectedly deploy if the air bag wiring harness gets chafed within the steering wheel and short circuits.

#### **Remedy**

Chrysler will notify owners, and dealers will inspect the air bag wiring within the steering wheel, replacing it if necessary. A protective cover will also be installed. These repairs will be made free of charge. The recall is expected to begin August 21, 2017. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is T47.

#### **Vehicle**

**MAKE MODEL YEAR**

**DODGE JOURNEY 2011-2015**

## Knee Air Bag Installed using Incorrect Bolts

**NHTSA Campaign Number:** 17V416000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** AIR BAGS

**Potential Number of Units Affected** 5

### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2016 Tundra vehicles. The affected vehicles have knee air bag mounting brackets with incorrect bolts.

### **Remedy**

All of the affected vehicles have been inspected and any incorrect knee air bag mounting bolts have been replaced, free of charge. Toyota's number for this recall is H0K.

### **Vehicle**

**MAKE MODEL YEAR**

TOYOTA TUNDRA 2016

## Headliner Missing Foam Blocks/FMVSS 201

**NHTSA Campaign Number:** 17V412000

**Manufacturer** General Motors LLC

## **Components STRUCTURE**

**Potential Number of Units Affected** 10

### **Summary**

General Motors LLC (GM) is recalling certain 2016-2017 Buick Envision vehicles. The affected vehicles received a repair that parts might not have had impact energy-absorbing foam blocks attached. As such, these vehicles fail to comply with the "Occupant protection in interior impact."

### **Remedy**

GM will notify owners, and dealers will replace the headliner assembly, free of charge. The manufacturer has not yet provided a phone number. Call 1-800-521-7300. GM's number for this recall is 17275.

### **Vehicle**

**MAKE MODEL YEAR**

BUICK ENVISION 2016-2017

## **Incorrectly Calibrated TPMS/FMVSS 138**

**NHTSA Campaign Number:** 17V411000

**Manufacturer** Aston Martin The Americas

**Components** TIRES

**Potential Number of Units Affected** 319

### **Summary**

Aston Martin the Americas (Aston Martin) is recalling certain 2017 DB11 vehicles. The affected vehicles have a tire pressure monitoring system (TPMS) in the low tire pressure warning tell-tale not illuminating at the required minimum activation pressure. As such, these vehicles do not meet the Federal Motor Vehicle Safety Standard (FMVSS) number 138, "Tire Pressure Monitoring Systems."

### **Remedy**

Aston Martin will notify owners, and dealers will update the TPMS software, free of charge. The recall is expected to be completed by 12/31/2017. Call 888-923-9988. Aston Martin's number for this recall is RA-13-0025.

### **Vehicle**

**MAKE      MODEL YEAR**

ASTON MARTIN DB11    2017

