



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

July 24, 2017

Door may Unlatch in a Side Impact Collision

NHTSA Campaign Number: 17V331000

Manufacturer Ford Motor Company

Components STRUCTURE, LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 14,410

Summary

Ford Motor Company (Ford) is recalling certain 2015-2017 F-150, and 2017 F-250, F-350, F-450, and F-550 vehicles originally produced with black or body colored exterior door handles that may have been subsequently equipped with a Putco chrome exterior door handle cover accessory kit purchased from a Ford dealer. These accessory door handle covers may cause the doors to unlatch in a side impact collision. As such, these vehicles may fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 206, "Door Locks and Door Retention Components."

Remedy

Ford will notify owners, and dealers will remove the accessory covers and refund the purchase price. The recall is expected to begin July 21, 2017. Owners may contact Ford at 1-866-436-7332. Ford's number for the recall is 17C09.

Vehicles

MAKE MODEL YEAR

FORD	F-150	2015-2017
FORD	F-250	2017
FORD	F-350	2017
FORD	F-450	2017
FORD	F-550	2017

Incorrect Wire Harness Installed on Front Air Bag

NHTSA Campaign Number: 17V417000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 629

Summary

Honda (American Honda Motor Co.) is recalling certain 2007-2011 Honda CR-V vehicles which have had the passenger frontal air bag replaced. The Takata air bag inflator repair kit may have been assembled by the supplier with an incorrect wire harness.

Remedy

Honda will notify owners, and dealers will inspect and, if necessary, replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin August 1, 2017. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is KF9.

Vehicle

MAKE MODEL YEAR

HONDA	CR-V	2007-2011
-------	------	-----------

Driver Frontal Air Bag Inflator May Rupture

.

NHTSA Campaign Number: 17V449000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 515,394

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2007-2011 Versa Sedan and 2007-2012 Versa Hatchback vehicles. The affected vehicles have a Takata driver frontal air bag inflator that may rupture due to propellant degradation occurring after long-term exposure to moderate absolute humidity, temperatures, and temperature cycling.

Remedy

Nissan will notify owners, and dealers will replace the subject inflator with a new one manufactured by a different supplier, free of charge. Remedy parts are not currently available. An interim owner notification letter will be sent by the end of September 2017, followed by a second letter when remedy parts are available. Owners may contact Nissan customer service at 1-800-647-7261.

Vehicle

MAKE MODEL YEAR

NISSAN VERSA 2007-2012

