



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

July 31, 2017

Passenger Frontal Air Bag Inflator May Rupture

NHTSA Campaign Number: 17V429000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 205,377

Summary

Mazda North America Operations (Mazda) is recalling certain 2009-2011 Mazda6, and 2007-2011 CX-7 and CX-9 vehicles. These vehicles are equipped with certain Takata air bag inflators assembled as part of the passenger frontal air bag modules, and used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the front air bags, these inflators may rupture due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Mazda will notify owners, and dealers will replace the passenger frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin July 24, 2017. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1317F.

Note: This recall supersedes recall 16V356 and all vehicles that were not remedied under that campaign are now covered by this one.

Vehicles

MAKE MODEL YEAR

MAZDA CX-7 2007-2011
MAZDA CX-9 2007-2011
MAZDA MAZDA6 2009-2011

Frontal Air Bags May Not Deploy

NHTSA Campaign Number: 17V437000

Manufacturer General Motors LLC

Components AIR BAGS, SEAT BELTS

Potential Number of Units Affected 40,683

Summary

General Motors LLC (GM) is recalling certain model year 2014-2016 Buick Lacrosse and Chevrolet Spark EV, Caprice PPV and SS vehicles, 2014-2017 Buick Encore and Chevrolet Corvette, Silverado 1500 and GMC Sierra 1500 vehicles, 2015-2016 Cadillac Escalade and Escalade ESV, Chevrolet Tahoe, Trax, Suburban and Silverado 2500 and 3500 and GMC Yukon and Yukon XL vehicles, and 2015-2017 GMC Sierra HD 2500 and 3500 vehicles. While being previously remedied for recall 16V-651, the affected vehicles may not have received the complete Delphi software update necessary to remedy the recall condition. Without the update, certain driving conditions may cause the air bag sensing and diagnostic module (SDM) software to activate a diagnostic test. During this test, deployment of the frontal air bags and the seat belt pretensioners would not occur in the event of a crash.

Remedy

GM will notify owners, and dealers will reflash the SDM software. Vehicles that have had a previous air bag deployment will have the SDM replaced. These repairs will be performed free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Buick customer service at 1-800-521-7300, Cadillac customer service at 1-800-458-8006,

Chevrolet customer service at 1-800-222-1020, or GMC customer service at 1-800-462-8782.
GM's number for this recall is 17287.

Vehicles

MAKE	MODEL	YEAR
BUICK	ENCORE	2014-2017
BUICK	LACROSSE	2014-2016
CADILLAC	ESCALADE	2015-2016
CADILLAC	ESCALADE ESV	2015-2016
CHEVROLET	CAPRICE POLICE PURSUIT	2014-2016
CHEVROLET	CORVETTE	2014-2017
CHEVROLET	SILVERADO 1500	2014-2017
CHEVROLET	SILVERADO 2500	2015-2016
CHEVROLET	SILVERADO 3500	2015-2016
CHEVROLET	SPARK EV	2014-2016
CHEVROLET	SS	2014-2016
CHEVROLET	SUBURBAN	2015-2016
CHEVROLET	TAHOE	2015-2016
CHEVROLET	TRAX	2015-2016
GMC	SIERRA 1500	2014-2017
GMC	SIERRA 2500	2015-2017
GMC	SIERRA 3500	2015-2017
GMC	YUKON	2015-2016
GMC	YUKON XL	2015-2016

Water Intrusion may cause Wiper Motor Failure

NHTSA Campaign Number: 17V461000

Manufacturer Mitsubishi Motors North America, Inc.

Components VISIBILITY

Potential Number of Units Affected 100,082

Summary

Mitsubishi Motors North America, Inc. (MMNA) is recalling certain 2007-2013 Outlander vehicles. In the affected vehicles, water may drop between the hood and the windshield and leak into the Denso wiper motor breathing hole. The water may cause internal corrosion of the windshield wiper motor and the possible failure of the motor.

Remedy

MMNA will notify owners, and dealers will replace the wiper motor, free of charge. The recall is expected to begin July 28, 2017. Owners may contact MMNA customer service at 1-888-648-7820. MMNA's number for this recall is SR-17-003.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

MITSUBISHI	OUTLANDER	2007-2013
------------	-----------	-----------