



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

August 28, 2017

### Incorrectly Welded Driver Air Bag Inflator

**NHTSA Campaign Number:** 17V495000

**Manufacturer** BMW of North America, LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 6,785

#### Summary

BMW of North America, LLC. (BMW) is recalling certain 2012-2013 BMW X3 xDrive28i, X3 xDrive35i, and M6 Convertible vehicles and 2013 M6 Coupe vehicles. The affected vehicles have a Takata driver's frontal air bag inflator that may have been improperly welded.

#### Remedy

BMW will notify owners, and dealers will replace the driver's front air bag module, free of charge. The recall is expected to begin October 9, 2017. Owners may contact BMW customer service at 1-800-525-7417.

#### MAKE MODEL YEAR

BMW	M6	2013
BMW	X3	2012-2013

