



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

September 4, 2017

[Driver's Frontal Air Bag May Rupture](#)

NHTSA Campaign Number: 17V474000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 308,992

Summary

Mazda North American Operations (Mazda) is recalling certain model year 2003-2008 Mazda6, 2004-2008 RX-8, and 2006-2007 Mazdaspeed6 vehicles. The affected vehicles are equipped with a dual-stage driver frontal air bag that may be susceptible to moisture intrusion and other factors, including manufacturing variability that, over time, could cause the inflator to rupture.

Remedy

Mazda will notify owners, and dealers will replace the driver's frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin September 1, 2017. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1417G. Note: This recall supersedes recall 15V-382.

Vehicles

| MAKE | MODEL | YEAR |
|-------------|--------------|-------------|
| MAZDA | MAZDA6 | 2003-2008 |
| MAZDA | MAZDASPEED6 | 2006-2007 |
| MAZDA | RX-8 | 2004-2008 |

ECU Software May Cause Engine Shut Down

NHTSA Campaign Number: 17V506000

Manufacturer Mercedes-Benz USA, LLC.

Components ENGINE AND ENGINE COOLING, ELECTRICAL SYSTEM

Potential Number of Units Affected 12,322

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016-2017 AMG GLE43 Coupe, and 2017 AMG GLE43 vehicles. The engine control unit and transmission control unit software may have compatibility conflicts and cause the engine to shut-down while the driver brakes to a stop, or accelerates following an ECO start.

Remedy

MBUSA will notify owners, and dealers will reprogram the engine and transmission control unit software, free of charge. The recall is expected to begin in September 2017. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicle

| MAKE | MODEL | YEAR |
|---------------|--------------|-------------|
| MERCEDES-BENZ | GLE43 | 2016-2017 |

Seat Belt may not Restrain in a Crash

NHTSA Campaign Number: 17V507000

Manufacturer BMW of North America, LLC

Components SEAT BELTS

Potential Number of Units Affected 67

Summary

BMW of North America, LLC (BMW) is recalling certain 2018 430i, 430i xDrive, 440i, 440i xDrive, and M4 convertible vehicles. The TRW ZF Emergency Locking Retractors (ELR) within the front seat belt assemblies may have been produced with incompatible vehicle-sensitive locking mechanism housings.

Remedy

BMW will notify owners, and dealers will inspect and, if necessary replace, the front seat belt assemblies, free of charge. The recall is expected to begin October 9, 2017. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

| | | |
|-----|------|------|
| BMW | 430I | 2018 |
| BMW | 440I | 2018 |
| BMW | M4 | 2018 |