



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

October 2, 2017

Insufficient Welds on Air Bag Inflator

NHTSA Campaign Number: 17V571000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 814

Summary

Nissan North America (Nissan) is recalling certain 2017 Infiniti Q50 and Q50 Hybrid vehicles. The Daicel driver's frontal air bag inflator may have been improperly welded.

Remedy

Nissan will notify owners, and dealers will replace the driver side air bag inflator, free of charge. The recall is expected to begin October 30, 2017. Owners may contact Infiniti customer service at 1-800-662-6200, option 7.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

INFINITI	Q50	2017
----------	-----	------

INFINITI	Q50 HYBRID	2017
----------	------------	------