



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

November 13, 2017

Excess Insulation Impairing Air Bag Deployment

NHTSA Campaign Number: 17V655000

Manufacturer Mercedes-Benz USA, LLC.

Components VISIBILITY, AIR BAGS

Potential Number of Units Affected 3,620

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016 GLE300d 4Matic, GLE400 4Matic, GLE350 4Matic, GLE63 AMG, GLE63 AMG Coupe, GLE63S AMG and GLE63S AMG Coupe, and 2017 GLS450 4Matic, GLE550 4Matic, and GLE63 AMG 4Matic vehicles. These vehicles may have excess bulkhead insulation extending into the lower windshield area, possibly affecting the windshield bonding and the deployment of the passenger's frontal air bag in the event of a crash.

Remedy

MBUSA will notify owners, and dealers will remove any excess bulkhead insulation and rework the windshield bonding, as necessary, free of charge. The recall is expected to begin in December 2017. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	GLE550	2017
MERCEDES BENZ	GLS450	2017
MERCEDES-BENZ	GLE300D	2016
MERCEDES-BENZ	GLE350	2016
MERCEDES-BENZ	GLE400	2016
MERCEDES-BENZ	GLE63	2016-2017
MERCEDES-BENZ	GLE63S	2016