



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

November 27, 2017

### Instrument Cluster Will Go Blank

**NHTSA Campaign Number:** 17V679000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 21,998

#### **Summary**

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2017 Land Rover Range Rover and Range Rover Sport vehicles. The Visteon Thin Film Transistor instrument cluster (IC) may intermittently go blank. The supply voltage to certain circuits within the assembly may become unstable at higher operating temperatures. This causes the software monitoring the of the voltage supply to record a fault and reset the Instrument cluster causing a temporary blank out.

#### **Remedy**

Land Rover will notify owners, and dealers will update the vehicle software, free of charge. The recall is expected to begin December 19, 2017. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is N124.

## Vehicles

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER	2017
LAND ROVER	RANGE ROVER SPORT	2017
JAGUAR	F-PACE	2017-2018
JAGUAR	XE	2018
JAGUAR	XF	2017-2018
JAGUAR	XJ	2016-2017