



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

November 6, 2017

### Improper Air Bag Inflation

**NHTSA Campaign Number:** 17V621000

**Manufacturer** General Motors LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 16

#### **Summary**

General Motors LLC (GM) is recalling certain 2015-2016 GMC Canyon and Chevrolet Colorado, and 2016 Chevrolet Volt vehicles. The Key Safety Systems driver's frontal air bag may improperly inflate during second-stage deployment in the event of a high speed crash.

#### **Remedy**

GM will notify owners, and dealers will replace the driver's frontal air bag module, free of charge. The recall is expected to begin November 10, 2017. Owners may contact Chevrolet customer service at 1-800-222-1020, or GMC customer service at 1-800-462-8782. GM's number for this recall is 17387.

#### **Vehicles**

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	COLORADO	2015-2016
-----------	----------	-----------

CHEVROLET	VOLT	2016
-----------	------	------

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
GMC	CANYON	2015-2016

## Blower Motor Wiring may Overheat

**NHTSA Campaign Number:** 17V676000

**Manufacturer** BMW of North America, LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 672,775

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2006-2011 323i, 325i, 325xi, 328i, 328xi, 330i, 330xi, 335i, 335xi and M3, 2007-2011 328i xDrive, 335i xDrive and 335is and 2009-2011 335d vehicles. The Leoni Bordnetz wiring and electrical connectors for the system that controls air flow for the heating and air conditioning system may overheat.

### **Remedy**

BMW will notify owners, and dealers will replace the wiring and electrical connectors, free of charge. The recall is expected to begin December 18, 2017. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

BMW	323I	2006-2011
BMW	325I	2006-2011
BMW	325XI	2006-2011
BMW	328I	2006-2011
BMW	328XI	2006-2011
BMW	330I	2006-2011
BMW	330XI	2006-2011
BMW	335D	2009-2011
BMW	335I	2006-2011
BMW	335IS	2007-2011
BMW	335XI	2006-2011
BMW	M3	2006-2011

## PCV Heater may Short Circuit

**NHTSA Campaign Number:** 17V683000

**Manufacturer** BMW of North America, LLC

**Components** ENGINE AND ENGINE COOLING

**Potential Number of Units Affected** 740,561

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2008-2011 128i and 2007-2011 328i, 328xi, 328i xDrive, 525i, 525xi, 528i, 528xi, 530i, 530xi, X3 3.0si, X3 xDrive30i, X5 xDrive30i, Z4 3.0i, Z4 3.0si and Z4 sDrive30i vehicles. The Mahle International heater for the positive crankcase ventilation (PCV) valve may short circuit.

### **Remedy**

BMW will notify owners, and dealers will replace the PCV valve heater, free of charge. The recall is expected to begin December 18, 2017. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicles**

#### **MAKE MODEL YEAR**

BMW	128I	2008-2011
BMW	328I	2007-2011
BMW	525I	2007-2011
BMW	528I	2007-2011
BMW	530I	2007-2011
BMW	X3	2007-2011
BMW	X5	2007-2011
BMW	Z4	2007-2011

## Inadvertent Driver Air Bag Deployment

**NHTSA Campaign Number:** 17V691000

**Manufacturer** Nissan North America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 17,507

## **Summary**

Nissan North America, Inc. (Nissan) is recalling 2017-2018 Infiniti QX30 vehicles. The driver's air bag may unexpectedly deploy due to insufficient grounding of the steering components if an electrostatic discharge occurs and the air bag clockspring is broken.

## **Remedy**

Nissan will notify owners, and dealers will add sufficient grounding to the steering components, free of charge. The recall is expected to begin December 18, 2017. Owners may contact Infiniti customer service at 1-800-622-6200, option 7.

## **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

INFINITI	QX30	2017-2018
----------	------	-----------