



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

January 22, 2018

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V004000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 10,166

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2010-2011 Audi A6 Avant, A6 Sedan and S6 Sedan vehicles, ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia, or "Zone B."

Additionally, unless included in "Zone B" above, Volkswagen is recalling certain 2009 Audi A4 Cabriolet and S4 Cabriolet vehicles, and 2009-2011 Audi A6 Avant, A6 Sedan and S6 Sedan vehicles registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Audi will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. Audi will send an interim owner notification on or before March 03, 2018. When parts to perform the recall repair become available, Audi will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin in June 2018. Owners may contact Audi customer service at 1-800-253-2834.

Vehicles

MAKE	MODEL	YEAR
AUDI	A4 CABRIOLET	2009
AUDI	A6	2009-2011
AUDI	S4 CABRIOLET	2009
AUDI	S6	2009-2011

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V007000

Manufacturer McLaren Automotive Incorporated

Components AIR BAGS

Potential Number of Units Affected 231

Summary

McLaren Automotive Incorporated (McLaren) is recalling certain 2013 MP4-12C vehicles ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

McLaren will notify owners, and dealers will replace the front passenger air bag inflator, free of charge. The recall is expected to begin January 22, 2018. Owners may contact McLaren customer service at 1-646-429-8916.

Vehicle

MAKE MODEL YEAR

MCLAREN MP4-12C 2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V009000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 8,925

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2013 Jaguar XF vehicles originally sold, or ever registered, in Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands, or "Zone A."

Unless included in "Zone A" above, Jaguar is recalling certain 2010 Jaguar XF vehicles, originally sold, or ever registered, in Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia, or "Zone B."

Unless included in Zone A and Zone B above, Jaguar is recalling certain 2009 MY Jaguar XF vehicles, originally sold, or ever registered, in Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Jaguar will notify owners, and dealers will replace the front passenger air bag assemblies, free of charge. The recall is expected to begin February 28, 2018. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is J071.

Vehicle

MAKE MODEL YEAR

JAGUAR XF 2009-2010, 2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V011000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 2,583

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2010 Land Rover Range Rover vehicles, originally sold, or ever registered, in Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia, or "Zone B."

Unless included in "Zone B" above, Land Rover is recalling certain 2009 Land Rover Range Rover vehicles, originally sold, or ever registered, in Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Land Rover will notify owners, and dealers will replace the front passenger air bag assembly, free of charge. The recall is expected to begin February 28, 2018. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is P083.

Vehicle

MAKE MODEL YEAR

LAND ROVER RANGE ROVER 2009-2010

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V012000

Manufacturer Subaru of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 64,179

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2009-2013 Legacy, Forester, Tribeca, WRX and Outback vehicles, and 2009-2011 Impreza vehicles sold, or ever registered, in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Subaru will notify owners, and dealers will replace the front passenger air bag inflator, free of charge. The recall is expected to begin February 9, 2018. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for this recall is TKA-18.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

SUBARU	FORESTER	2009-2013
--------	----------	-----------

SUBARU	IMPREZA	2009-2011
--------	---------	-----------

SUBARU	LEGACY	2009-2013
--------	--------	-----------

SUBARU	OUTBACK	2009-2013
--------	---------	-----------

SUBARU	TRIBECA	2009-2013
--------	---------	-----------

SUBARU	WRX	2009-2013
--------	-----	-----------

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V013000

Manufacturer Subaru of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 93,209

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2009-2010 Tribeca, Impreza, Forester, WRX, Legacy, and Outback vehicles sold, or ever registered, in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Subaru will notify owners, and dealers will replace the front passenger air bag inflator, free of charge. The recall is expected to begin February 9, 2018. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for this recall is TKB-18.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

SUBARU	FORESTER	2009-2010
SUBARU	IMPREZA	2009-2010
SUBARU	LEGACY	2009-2010
SUBARU	OUTBACK	2009-2010
SUBARU	TRIBECA	2009-2010
SUBARU	WRX	2009-2010

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V014000

Manufacturer Subaru of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 72,150

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2009 Tribeca, Impreza, Forester, WRX, Legacy, and Outback vehicles sold, or ever registered, in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Subaru will notify owners, and dealers will replace the front passenger air bag inflators, free of charge. The recall is expected to begin February 9, 2018. Owners may contact Subaru customer service at 1-800-782-2783. Subaru's number for this recall is TKC-18.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

SUBARU	FORESTER	2009
SUBARU	IMPREZA	2009
SUBARU	LEGACY	2009
SUBARU	OUTBACK	2009
SUBARU	TRIBECA	2009
SUBARU	WRX	2009

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V015000

Manufacturer Jaguar Land Rover North America, LLC

Components AIR BAGS

Potential Number of Units Affected 8,480

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2011-2012 Land Rover Range Rover vehicles, originally sold, or ever registered, in Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia, or "Zone B."

Unless included in "Zone B" above, Land Rover is recalling certain 2010-2012 Land Rover Range Rover

vehicles, originally sold, or ever registered, in Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Land Rover will notify owners, and dealers will replace the front passenger air bag assembly, free of charge. The recall is expected to begin February 28, 2018. Owners may contact Land Rover customer service at 1-800-637-6837. Land Rover's number for this recall is P084.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

LAND ROVER	RANGE ROVER	2010-2012
------------	-------------	-----------

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V016000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 84

Summary

Mazda North American Operations (Mazda) is recalling certain 2009 B-Series trucks ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate inflator, free of charge. The recall is expected to begin March 9, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 2118A.

Vehicle

MAKE MODEL YEAR

MAZDA B-SERIES TRUCK 2009

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V017000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 607

Summary

Mazda North American Operations (Mazda) is recalling 2010 Mazda RX-8 vehicles sold, or ever registered, in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Additionally, unless covered under "Zone B" Mazda is recalling certain 2009 RX-8 vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate one, free of charge. The recall is expected to begin March 9, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 2018A.

Vehicle

MAKE MODEL YEAR

MAZDA RX-8 2009-2010

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V018000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 70,227

Summary

Mazda North American Operations (Mazda) is recalling certain 2013 Mazda6 and CX-9 vehicles sold, or ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, unless covered in "Zone A," Mazda is recalling certain 2010 Mazda6, CX-7 and CX-9 vehicles sold, or ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Additionally, unless covered in Zone A or Zone B, Mazda is recalling certain 2009 Mazda6, CX-7, and CX-9 vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate inflator, free of charge. The recall is expected to begin March 9, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 1317F.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

MAZDA	CX-7	2009-2010
-------	------	-----------

MAZDA	CX-9	2009-2010, 2013
-------	------	-----------------

MAZDA	MAZDA6	2009-2010, 2013
-------	--------	-----------------

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V021000

Manufacturer Chrysler (FCA US LLC)

Components AIR BAGS

Potential Number of Units Affected 317,000

Summary

Chrysler (FCA US LLC) is recalling certain 2009-2013 Jeep Wrangler, Chrysler 300, Dodge Challenger and Dodge Charger vehicles, and 2009-2011 Dodge Dakota vehicles sold, or ever registered, in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, Chrysler is recalling certain 2009-2010 RAM 4500 Cab Chassis, RAM 5500 Cab Chassis, RAM 3500 Cab Chassis, Jeep Wrangler, Chrysler 300, Dodge Dakota, Dodge Challenger, and Dodge Charger vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Chrysler is also recalling certain 2009 RAM 3500, RAM 2500, RAM 4500 Cab Chassis, RAM 5500 Cab Chassis, Dodge Durango, Chrysler Aspen, RAM 3500 Cab Chassis, Jeep Wrangler, Chrysler 300, Dodge Dakota, Dodge Challenger, and Dodge Charger vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming.

In the event of a crash necessitating deployment of the passenger frontal air bag, these passenger air bag inflator may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Chrysler will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin February 28, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U03.

Vehicles

MAKE	MODEL	YEAR
CHRYSLER	300	2009-2013
CHRYSLER	ASPEN	2009
DODGE	CHALLENGER	2009-2013
DODGE	CHARGER	2009-2013
DODGE	DAKOTA	2009-2011

MAKE	MODEL	YEAR
DODGE	DURANGO	2009
JEEP	WRANGLER	2009-2013
RAM	2500	2009
RAM	3500	2009-2010
RAM	4500	2009-2010
RAM	5500	2009-2010

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V024000

Manufacturer Toyota Motor Engineering & Manufacturing

Components AIR BAGS

Potential Number of Units Affected 601,259

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2013 Scion xB, Toyota Corolla, Corolla Matrix, Sienna, 4Runner, Lexus IS250, IS350, IS250C, IS350C, IS-F, and GX460 vehicles sold, ever registered, in the states of AL, CA, FL, GA, HI, LA, MS, SC, TX, PR, AS, GU, the MP (Saipan), and the U.S. VI or "Zone A."

Toyota is also recalling certain 2010 Scion xB, Toyota Corolla, Corolla Matrix, Yaris, 4Runner, Lexus IS250, IS350, IS250C, IS350C, ES350, IS-F, GX460, and Pontiac Vibe vehicles sold, ever registered, in the states of AZ, AR, DE, DC, IL, IN, KS, KY, MD, MO, NE, NV, NJ, NM, NC, OH, OK, PA, TN, VA, and WV or "Zone B."

Toyota is also recalling certain 2009 Scion xB, Toyota Corolla, Corolla Matrix, Yaris, Lexus IS250, IS350, ES350, IS-F, and Pontiac Vibe vehicles ever registered in the states of AK, CO, CT, ID, IA, ME, MA, MI, MN, MT, NH, NY, ND, OR, RI, SD, UT, VT, WA, WI, and WY or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Toyota will notify the Toyota, Scion and Lexus owners. General Motors will contact the Pontiac owners. Depending on the vehicle model, dealers will replace the front passenger air bag inflator, or replace the air bag assembly. The recall is expected to begin January 24, 2018. Owners may contact Toyota customer service at 1-800-331-4331, or Pontiac customer service at 1-800-762-2737. Toyota's numbers for this recall are "Zone A" Toyota: G0P, Lexus: GLG; "Zone B" Toyota: G0R, Lexus GLH; "Zone C" Toyota: H0A, and Lexus: HLA.

Vehicles

MAKE	MODEL	YEAR
LEXUS	ES350	2009-2010
LEXUS	GX460	2010, 2013
LEXUS	IS 250	2009-2010, 2013
LEXUS	IS 250C	2010, 2013
LEXUS	IS 350	2009-2010, 2013
LEXUS	IS 350C	2010, 2013
LEXUS	IS F	2009-2010, 2013
PONTIAC	VIBE	2009-2010
SCION	XB	2009-2010, 2013
TOYOTA	4RUNNER	2010, 2013
TOYOTA	COROLLA	2009-2010, 2013
TOYOTA	COROLLA MATRIX	2009-2010, 2013
TOYOTA	SIENNA	2013
TOYOTA	YARIS	2009-2010

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V025000

Manufacturer Toyota Motor Engineering & Manufacturing

Components AIR BAGS

Potential Number of Units Affected 14,585

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2010-2012 Yaris vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma,

Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Additionally, these vehicles are also being recalled in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming, or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Toyota will notify owners, and dealers will replace the passenger frontal air bag assemblies, free of charge. The recall is expected to begin by March 10, 2018. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are G0R (Zone B), and H0A (Zone C).

Vehicle

MAKE MODEL YEAR

TOYOTA YARIS 2010-2012

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V030000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 41,808

Summary

BMW of North America, LLC (BMW) is recalling certain 2007-2013 X5 xDrive30i, X5 xDrive35i, X5 xDrive48i, X5 xDrive50i, X5 M, 2009-2010 X5 xDrive35d vehicles and 2009-2013 X6 xDrive35i, X6 xDrive50i, and X6 M vehicles ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

BMW is also recalling certain 2007-2010 X5 xDrive30i, X5 xDrive35i, X5 xDrive48i, X5 xDrive50i, X5 M, X5 xDrive35d, X6 xDrive35i, X6 xDrive50i and X6M vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and

West Virginia or "Zone B."

BMW is also recalling certain 2007-2009 X5 xDrive30i, X5 xdrive35i, X5 xDrive48i, X5 xDrive50i, X5 M, X5 xDrive35d, X6 xDrive35i, X6 xDrive50i and X6M vehicles ever registered in the states of AK, CO, CT, ID, IA, ME, MA, MI, MN, MT, NH, NY, ND, OR, RI, SD, UT, VT, WA, WI, and WY or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

BMW will notify owners, and dealers will replace the passenger front air bag module, free of charge. The recall is expected to begin March 1, 2018. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

BMW	X5	2007-2013
BMW	X6	2009-2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V031000

Manufacturer Tesla, Inc.

Components AIR BAGS

Potential Number of Units Affected 17,846

Summary

Tesla, Inc. (Tesla) is recalling all 2013 Model S vehicles equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Tesla will notify owners, and Tesla Service Centers will replace the passenger frontal air bag modules, free of charge. The recall is expected to begin in early March 2018. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-18-20-001.

Vehicle

MAKE MODEL YEAR

TESLA MODEL S 2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V032000

Manufacturer Daimler Vans USA, LLC

Components AIR BAGS

Potential Number of Units Affected 17,413

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2013 Freightliner Sprinter 2500 and 3500 and Mercedes-Benz Sprinter 2500 and 3500 vehicles.

These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

DVUSA will notify owners, and dealers will replace the front passenger air bag module, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact DVUSA customer service at 1-877-762-8267.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

FREIGHTLINER	SPRINTER 2500	2013
--------------	---------------	------

FREIGHTLINER	SPRINTER 3500	2013
--------------	---------------	------

Driver Side Air Bag Inflator May Explode

NHTSA Campaign Number: 18V038000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 160

Summary

Mazda North American Operations (Mazda) is recalling certain 2006 B-Series vehicles. Upon deployment of the driver side frontal air bag, excessive internal pressure may cause the inflator to explode.

Remedy

Mazda will notify owners instructing them to not drive their vehicles, and dealers will replace the front driver side air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 19, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 2218A.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

MAZDA	B-SERIES TRUCK	2006
-------	----------------	------

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V039000

Manufacturer Mazda North American Operations

Components AIR BAGS

Potential Number of Units Affected 160

Summary

Mazda North America Operations (Mazda) is recalling certain 2006 B-Series vehicles. Upon deployment of the passenger side frontal air bag, excessive internal pressure may cause the inflator to explode.

Remedy

Mazda will notify owners instructing them not to drive their vehicles. Dealers will replace the passenger's frontal air bag inflator with an alternate inflator, free of charge. The recall is expected to begin January 19, 2018. Owners may contact Mazda customer service at 1-800-222-5500. Mazda's number for this recall is 2318A.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

MAZDA	B-SERIES TRUCK	2006
-------	----------------	------

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V040000

Manufacturer Ferrari North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 1,073

Summary

Ferrari North America, Inc. (Ferrari) is recalling certain 2013 California, 458 Italia, 458 Spider, FF, and F12 Berlinetta vehicles sold, or ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands. These vehicles are equipped with certain air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Ferrari will notify owners, and dealers will replace the passenger frontal air bag assembly, free of charge. The recall is expected to begin March 9, 2018. Owners may contact Ferrari customer service at 1-866-551-2828. Ferrari's number for this recall is 63.

Vehicles

MAKE	MODEL	YEAR
FERRARI	458	2013
FERRARI	CALIFORNIA	2013
FERRARI	F12 BERLINETTA	2013
FERRARI	FF	2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V041000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 24,945

Summary

Honda (American Honda Motor Co.) is recalling certain 2010-2012 Acura RL, 2010 Honda Element, and 2010-2013 Honda Ridgeline vehicles ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, Honda is recalling certain 2010 Acura RL, 2010-2011 Honda Element and Honda Ridgeline vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

If not included in zones A or B above, Honda is recalling certain 2009 Acura RL, Honda Element, and Honda Ridgeline vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the frontal air bag modules, and used as original equipment or replacement equipment (such as after a vehicle crash necessitating replacement of the original air bags), may explode due to propellant degradation occurring after long-term exposure to higher absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin February 12, 2018. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are U0H, and G0I.

Vehicles

MAKE	MODEL	YEAR
ACURA	RL	2009-2012
HONDA	ELEMENT	2009-2011
HONDA	RIDGELINE	2009-2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V042000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 691,726

Summary

Honda (American Honda Motor Co.) is recalling certain 2010-2013 Acura TSX, ZDX, Honda Accord Crosstour, Fit, Insight and Pilot vehicles, 2011-13 Acura TSX Sportswagon, 2010-2012 Honda Accord., 2010-2011 Honda Civic, Civic NGV, Civic Hybrid and CR-V vehicles and 2013 Honda FCX Clarity and Fit EV vehicles ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, Honda is recalling certain 2010-2012 Acura TSX, Honda Accord, Accord Crosstour, Fit and Pilot, 2010-2011 Honda Civic, Civic NGV, Civic Hybrid and CR-V, and 2010 Acura ZDX and Honda Insight vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Unless included in Zones A or B above, Honda is recalling certain 2009 Acura TSX, Honda Accord, Civic, Civic NGV, Civic Hybrid, CR-V, Fit, and Pilot vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with certain air bag inflators assembled as part of the frontal air bag modules, and used as original equipment or replacement equipment (such as after a vehicle crash necessitating replacement of the original air bags), may explode due to propellant degradation occurring after long-term exposure to higher absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin February 12, 2018. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are B0K and L0J.

Vehicles

MAKE	MODEL	YEAR
ACURA	TSX	2009-2013
ACURA	TSX SPORTSWAGON	2011-2013
ACURA	ZDX	2010-2013
HONDA	ACCORD	2009-2012
HONDA	ACCORD CROSSTOUR	2010-2013
HONDA	CIVIC	2009-2011
HONDA	CIVIC HYBRID	2009-2011
HONDA	CR-V	2009-2011
HONDA	FCX CLARITY	2013
HONDA	FIT	2009-2013
HONDA	FIT EV	2013
HONDA	INSIGHT	2010-2013
HONDA	PILOT	2009-2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V043000

Manufacturer Mercedes-Benz USA, LLC.

Components AIR BAGS

Potential Number of Units Affected 132,167

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2013 C250, C250 Coupe, C350 Coupe 4Matic, C300 4Matic, C350, C350 Coupe, C63 AMG, C63 Coupe, E350 Cabrio, E350 Coupe, E550 Cabrio, E350 Coupe 4Matic, E550 Coupe, GLK350 4Matic, GLK250 Bluetec 4Matic, GLK350, SLS Coupe, SLS AMG GT Coupe, and SLS Roadster vehicles sold, or ever registered, in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, MBUSA is recalling certain 2010 C300, C300 4Matic, C63 AMG, E350 Coupe, E550 Coupe, GLK350, and GLK350 4Matic vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

MBUSA is also recalling certain 2009 C300, C300 4Matic, C63 AMG, and C350 vehicles ever registered in the states of AK, CO, CT, ID, IA, ME, MA, MI, MN, MO, NH, NY, ND, OR, RI, SD, UT, VT, WA, WI and WY or "Zone C."

In the event of a crash necessitating deployment of the passenger frontal air bag, these passenger air bag inflator may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

MBUSA will notify owners, and dealers will replace the passenger frontal air bag module, free of charge. Parts are currently not available. Owners will be sent an interim notification starting in February 2018. A second notice will be mailed when remedy parts are available. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	C250	2013
MERCEDES BENZ	C300	2009-2010, 2013
MERCEDES BENZ	C350	2009, 2013
MERCEDES BENZ	C63 AMG	2009-2010, 2013
MERCEDES BENZ	E350	2010, 2013
MERCEDES BENZ	E550	2010, 2013
MERCEDES BENZ	GLK250	2013
MERCEDES BENZ	GLK350	2010, 2013
MERCEDES BENZ	SLS	2013

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V044000

Manufacturer Nissan North America, Inc.

Components AIR BAGS

Potential Number of Units Affected 52,614

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2009-2012 Versa Hatchback, and 2009-2011 Versa Sedan vehicles ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, Nissan is recalling certain 2009-2010 Versa Hatchback, and Versa Sedan vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Nissan is also recalling certain 2009 Versa Hatchback and Versa Sedan vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

In the event of a crash necessitating deployment of the passenger frontal air bag, these passenger air bag inflator may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

Remedy

Nissan will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Nissan customer service at 1-800-647-7261.

Vehicle

MAKE MODEL YEAR

NISSAN VERSA 2009-2012

Air Bag Inflator May Explode

NHTSA Campaign Number: 18V045000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 960

Summary

Honda (American Honda Motor Co.) is recalling certain 2009-2010 and 2012-2016 Honda GL1800 Gold Wing motorcycles. These motorcycles have air bag inflators assembled as part of the air bag module that may explode due to propellant degradation occurring after long-term exposure to higher absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the air bag module, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Honda Motorcycle Customer Support at 1-866-784-1870. Honda's number for this recall is KJ1.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

HONDA	GL1800	2009-2010, 2012-2016
-------	--------	----------------------

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 18V046000

Manufacturer Ford Motor Company

Components AIR BAGS

Potential Number of Units Affected 327,796

Summary

Ford Motor Company (Ford) is recalling certain 2013 Ford Mustang vehicles sold, or ever registered in the states of Alabama, California, Florida, Georgia, Hawaii, Louisiana, Mississippi, South Carolina, Texas, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands or "Zone A."

Additionally, Ford is recalling certain 2010 Ford Edge, Fusion, Mustang and Ranger, Lincoln MKX and Zephyr/MKZ, and Mercury Milan vehicles ever registered in the states of Arizona, Arkansas, Delaware, District of Columbia, Illinois, Indiana, Kansas, Kentucky, Maryland, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, Tennessee, Virginia, and West Virginia or "Zone B."

Ford is also recalling certain 2009 Ford Edge, Fusion, Mustang and Ranger, Lincoln MKX and Zephyr/MKZ, and Mercury Milan vehicles ever registered in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming or "Zone C."

These vehicles are equipped with air bag inflators assembled as part of the passenger frontal air bag modules, used as original equipment or replacement equipment (such as after a vehicle crash necessitating replacement of the original air bags), that may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy

Ford will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin February 19, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S01.

Vehicles

MAKE	MODEL	YEAR
FORD	EDGE	2009-2010
FORD	FUSION	2009-2010
FORD	MUSTANG	2009-2010, 2013
FORD	RANGER	2009-2010
LINCOLN	MKX	2009-2010
LINCOLN	MKZ	2009-2010
MERCURY	MILAN	2009-2010