



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

January 8, 2018

Door May Not Lock/ FMVSS 206

NHTSA Campaign Number: 17V816000

Manufacturer Mercedes-Benz USA, LLC.

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 8,700

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2017 GLE400 4Matic, GLE350 4Matic, GLE350, GLE550e 4Matic, GLE43 AMG 4Matic, GLE63 AMG 4Matic, GLS450, GLE63S 4Matic, GLS63 4Matic, S550e, S600, S63 AMG 4Matic, S65 AMG, S550, Mercedes-Maybach S600, Mercedes-Maybach S550 4Matic, GLE43 AMG 4Matic Coupe, GLE63S 4Matic Coupe, 2017-2018 GLS550 4Matic, S550 4Matic, 2018 S450, and S63 AMG 4Matic vehicles. The rear passenger door on the driver side may indicate that it is locked, when it may not be. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 206, "Door Locks and Door Retention Components."

Remedy

MBUSA will notify owners, and dealers will inspect the left rear door lock, replacing it as necessary, free of charge. The recall is expected to begin in January 2017. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	GLE350	2017
MERCEDES BENZ	GLE400	2017
MERCEDES BENZ	GLE43	2017
MERCEDES BENZ	GLE550E	2017
MERCEDES BENZ	GLE63	2017
MERCEDES BENZ	GLE63S	2017
MERCEDES BENZ	GLS450	2017
MERCEDES BENZ	GLS550	2017-2018
MERCEDES BENZ	GLS63	2017
MERCEDES BENZ	S450	2018
MERCEDES BENZ	S550	2017
MERCEDES BENZ	S550E	2017
MERCEDES BENZ	S600	2017
MERCEDES BENZ	S63	2017-2018
MERCEDES BENZ	S65 AMG	2017
MERCEDES-BENZ	S550 4MATIC	2017
MERCEDES-MAYBACH	S550	2017
MERCEDES-MAYBACH	S600	2017

Brake Booster May Not Provide Power Assist

NHTSA Campaign Number: 17V817000

Manufacturer Mercedes-Benz USA, LLC.

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 432

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain model year 2017 Mercedes G550 & G550 4x4 Squared vehicles. The vacuum hose for the brake booster may collapse resulting in increased braking effort.

Remedy

MBUSA will notify owners, and dealers will replace the vacuum hose, as necessary, free of charge. Parts are not currently available. Owners will be notified of the recall in January 2018 and they will receive a second letter when the parts become available, currently expected to be in March 2018. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

MERCEDES BENZ G550	2017
--------------------	------

Air Bag Nondeployment or Incorrect Deployment

NHTSA Campaign Number: 17V818000

Manufacturer Mercedes-Benz USA, LLC.

Components AIR BAGS

Potential Number of Units Affected 10

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2017 AMG GT & AMG GT-C Roadster and 2018 AMG GT-S & GT Roadster vehicles equipped with AMG Performance Seats. The passenger occupant classification system (OCS) might not function properly, possibly causing the passenger frontal air bag to be incorrectly deactivated or incorrectly activated in the event of a crash.

Remedy

MBUSA will notify owners, and dealers will update the OCS software, and if necessary, replace the passenger seat cushion, free of charge. Owners will be notified of the recall in January 2018 and they will receive a second letter when the parts become available, currently expected to be in February 2018. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	AMG GT	2017
MERCEDES BENZ	AMG GT C ROADSTER	2017
MERCEDES BENZ	AMG GT ROADSTER	2018
MERCEDES BENZ	AMG GT S	2018

Insufficient Low Beam Illumination/FMVSS 108

NHTSA Campaign Number: 17V819000

Manufacturer Mercedes-Benz USA, LLC.

Components EXTERIOR LIGHTING

Potential Number of Units Affected 8,134

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2016-2017 GLC300, GLC300 4MATIC and GLC43 4MATIC vehicles. These vehicles may have misadjusted headlights, possibly resulting in the low beam headlights insufficiently illuminating the roadway. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices, and Associated Equipment."

Remedy

MBUSA will notify owners, and dealers will inspect the headlamp adjustment, adjusting it as necessary, free of charge. The recall is expected to begin in January 2018. Owners may contact MBUSA customer service at 1-877-496-3691.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	GLC300	2016-2017
MERCEDES BENZ	GLC43 AMG	2016-2017