



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

February 5, 2018

Parking Brake Actuators may Corrode

NHTSA Campaign Number: 18V070000

Manufacturer Mitsubishi Motors North America, Inc.

Components PARKING BRAKE

Potential Number of Units Affected 170,354

Summary

Mitsubishi Motors North America, Inc. (MMNA) is recalling certain 2014-2016 Outlander and 2013-2016 Outlander Sport vehicles. Water may enter the rear brake calipers causing the parking brake actuator shafts to corrode and possibly bind.

Remedy

MMNA will notify owners, and dealers will inspect the rear brake calipers and replace the parking brake boot and lever or the brake caliper body, as necessary. Dealers will also replace the piston assembly of the rear brake caliper. These repairs will be performed free of charge. The recall is expected to begin March 27, 2018. Owners may contact MMNA customer service at 1-888-648-7820. MMNA's number for this recall is SR-18-002.

Vehicles

MAKE	MODEL	YEAR
MITSUBISHI	OUTLANDER	2014-2016
MITSUBISHI	OUTLANDER SPORT	2013-2016

Sun Roof Glass may Detach from Assembly

NHTSA Campaign Number: 18V071000

Manufacturer Mitsubishi Motors North America, Inc.

Components VISIBILITY

Potential Number of Units Affected 56,641

Summary

Mitsubishi Motors North America, Inc. (MMNA) is recalling certain 2007-2010 Outlander, 2008-2010 Lancer, 2009-2010 Lancer Evolution, and 2010 Lancer Sportback vehicles equipped with sunroofs. The sunroof glass may detach from the sunroof assembly, becoming a road hazard to other vehicles.

Remedy

MMNA will notify owners, and dealers will replace the sunroof glass assembly, free of charge. The recall is expected to begin March 27, 2018. Owners may contact MMNA customer service at 1-888-648-7820. MMNA's number for this recall is SR-18-003.

Vehicles

MAKE	MODEL	YEAR
MITSUBISHI	LANCER	2008-2010
MITSUBISHI	LANCER EVOLUTION	2009-2010
MITSUBISHI	LANCER SPORTBACK	2010
MITSUBISHI	OUTLANDER	2007-2010