



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

June 25, 2018

[Seat Belt Anchorage Detachment/FMVSS 210, 209, 208](#)

NHTSA Campaign Number: 18V355000

Manufacturer Nissan North America, Inc.

Components SEAT BELTS

Potential Number of Units Affected 6

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2018 Infiniti QX30 vehicles. The bolt securing the right-hand side lower seat belt anchorage may have been incorrectly installed during production. This can result in the lower seat belt anchorage detaching in a crash. As such, these vehicles fail to comply with certain requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 210, "Seat Belt Assembly Anchorages", number 209, "Seat Belt Assemblies, and number 208, "Occupant Crash Protection."

Remedy

Nissan will notify owners, and dealers will weld in a new retaining plate and secure the seat belt anchorage with a new anchor bolt, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Infiniti customer service at 1-800-662-6200.

Vehicle

MAKE MODEL YEAR

INFINITI QX30 2018

Hard Braking and Acceleration may Disable Air Bags

NHTSA Campaign Number: 18V360000

Manufacturer General Motors LLC

Components AIR BAGS

Potential Number of Units Affected 498

Summary

General Motors LLC (GM) is recalling certain 2019 Chevrolet Corvette ZR1 vehicles. Hard braking or acceleration may cause the Aptiv sensing diagnostic module (SDM) to enter a fault state. As a result, the SDM will not provide crash sensing or deploy the necessary air bags in the event of a crash.

Remedy

GM will notify owners, and dealers will reprogram the SDM with updated software, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is 18195.

Vehicle

MAKE MODEL YEAR

CHEVROLET CORVETTE 2019

Unintentional Vehicle Movement/FMVSS 114

NHTSA Campaign Number: 18V395000

Manufacturer Chrysler (FCA US LLC)

Components ELECTRICAL SYSTEM, EQUIPMENT

Potential Number of Units Affected 240,242

Summary

Chrysler (FCA US LLC) is recalling certain 2017-2018 Chrysler Pacifica vehicles. The Yanfeng Manual Park Release (MPR) plug may be removed without a tool. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 114, "Theft Protection."

Remedy

Chrysler will notify owners, and dealers will replace the MPR plug, free of charge. The recall is expected to begin August 3, 2018. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is U50.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

CHRYSLER	PACIFICA	2017-2018
----------	----------	-----------

Loss of Propulsion Power in Low Voltage Condition

NHTSA Campaign Number: 18V397000

Manufacturer General Motors LLC

Components HYBRID PROPULSION SYSTEM

Potential Number of Units Affected 3,233

Summary

General Motors LLC (GM) is recalling certain 2013 Chevrolet Volt vehicles. An update to the Hybrid Powertrain Control Module 2 (HPCM2) may have disabled the cell balancing function causing a low-voltage condition.

Remedy

GM will notify owners, and dealers will reprogram the HPCM2, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is 18215.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

CHEVROLET VOLT	2013
----------------	------