

# NHTSA Recalls of Interest July 9, 2018

## Passenger Frontal Air Bag May Deploy Improperly

NHTSA Campaign Number: 18V375000

Manufacturer Volkswagen Group of America, Inc.

**Components** AIR BAGS

Potential Number of Units Affected 821

#### Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen Atlas and Tiguan vehicles. In the event of a crash, the Key Safety Systems passenger frontal air bag may tear or not properly unfold during deployment.

#### Remedy

Volkswagen will notify owners, and dealers will replace the passenger frontal air bag, free of charge. The recall is expected to begin August 3, 2018. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's numbers for this recall are 69W8, and 69W9.

#### Vehicles

#### MAKE MODEL YEAR

VOLKSWAGEN ATLAS 2018 VOLKSWAGEN TIGUAN 2018

### Passenger Frontal Air Bag Inflator May Explode

#### NHTSA Campaign Number: 18V402000

Manufacturer Mazda North American Operations

**Components AIR BAGS** 

Potential Number of Units Affected 269,618

#### Summary

Mazda North America Operations (Mazda) is recalling certain 2003-2008 Mazda6, 2006-2007 Mazdaspeed6 and 2004 MPV vehicles nationwide. Mazda is also recalling 2005-2006 MPV vehicles in Alabama, Arizona, Arkansas, California, Delaware, the District of Columbia, Florida, Georgia, Hawaii, Illinois, Indiana, Kansas, Kentucky, Louisiana, Maryland, Mississippi, Missouri, Nebraska, Nevada, New Jersey, New Mexico, North Carolina, Ohio, Oklahoma, Pennsylvania, South Carolina, Tennessee, Texas, Virginia, West Virginia, Puerto Rico, American Samoa, Guam, the Northern Mariana Islands (Saipan), and the U.S. Virgin Islands. These vehicles are equipped with certain Takata air bag inflators assembled as part of the passenger frontal air bag modules, and used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these passenger air bag inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

#### Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate inflator, free of charge. The recall is expected to begin in July 2018. Owners may contact Mazda customer service at 1-800-222-5500 ,Option 4. Mazda's number for this recall is 2618F. Note: This recall partially supersedes recall 16V354.

#### Vehicles

MAKE	MODEL	YEAR
MAZDA	MAZDA6	2003-2008
MAZDA	MAZDASPEED6	2006-2007
MAZDA	MPV	2004-2006

## Passenger Frontal Air Bag Inflator May Explode

#### NHTSA Campaign Number: 18V404000

Manufacturer Mazda North American Operations

**Components** AIR BAGS

**Potential Number of Units Affected** 2,539

#### Summary

Mazda North America Operations (Mazda) is recalling certain 2005-2006 Mazda MPV vehicles sold, or ever registered, in the states of Alaska, Colorado, Connecticut, Idaho, Iowa, Maine, Massachusetts, Michigan, Minnesota, Montana, New Hampshire, New York, North Dakota, Oregon, Rhode Island, South Dakota, Utah, Vermont, Washington, Wisconsin, and Wyoming.

These vehicles are equipped with certain Takata air bag inflators assembled as part of the passenger frontal air bag modules used as original equipment or replacement equipment. In the event of a crash necessitating deployment of the passenger frontal air bag, these inflators may explode due to propellant degradation occurring after long-term exposure to absolute humidity and temperature cycling.

#### Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate inflator, free of charge. The recall is expected to begin July 2018. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 2618F. Note: This recall partially supersedes recall 17V011.

#### Vehicle

#### MAKE MODEL YEAR

MAZDA MPV 2005-2006