



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

December 10, 2018

Seat Track Sensor Out of Position

NHTSA Campaign Number: 18V822000

Manufacturer Chrysler (FCA US LLC)

Components SEATS

Potential Number of Units Affected 23

Summary

Chrysler (FCA US LLC) is recalling certain 2019 RAM 1500 trucks. The Adient seat track position sensor on the manually-adjusted passenger seats may come loose and out of position, preventing the sensor from detecting if the seat is in the full-forward position.

Remedy

Chrysler will notify owners and dealers will inspect the passenger seat track position sensor bracket, replacing it as necessary, free of charge. The recall is expected to begin January 9, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is UB7.

Vehicle

MAKE MODEL YEAR

RAM 1500 2019

No Warning When Key is Left in Ignition/FMVSS 114

NHTSA Campaign Number: 18V824000

Manufacturer Volkswagen Group of America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 73,545

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018-2019 Volkswagen Atlas and Tiguan and 2019 Volkswagen Jetta vehicles that do not have keyless entry. The instrument cluster may not provide an audible warning to let the driver know that the key is still in the ignition when the door is open. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 114, "Theft Protection."

Remedy

Volkswagen will notify owners, and dealers will reprogram the instrument cluster, free of charge. The recall is expected to begin January 18, 2019. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's numbers for this recall are 90L3 and 90L4.

Vehicles

MAKE	MODEL	YEAR
VOLKSWAGEN	ATLAS	2018-2019
VOLKSWAGEN	JETTA	2019
VOLKSWAGEN	TIGUAN	2018-2019

Seat Belts Incorrectly Detected as Unfastened

NHTSA Campaign Number: 18V839000

Manufacturer Mercedes-Benz USA, LLC.

Components SEAT BELTS

Potential Number of Units Affected 5,433

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019 C300 4Matic Cabriolet, C43 AMG Cabriolet, C300 Cabriolet, C300 Coupe, C300 4Matic Coupe, C43 AMG Coupe, E450 Coupe, E53 AMG Cabriolet, S450, S560, E450 Cabriolet, E450 4Matic Cabriolet, E450 4Matic Coupe, E53 AMG Coupe, S450 4Matic, S560 4Matic, S63 AMG and S65 AMG vehicles and Mercedes-Mayback S650 and S560 4 Matic vehicles. A ZF

correctly fastened seatbelt may be inaccurately detected as being unfastened, preventing the seat belt pretensioners from activating in the event of a crash.

Remedy

MBUSA will notify owners, and dealers will replace the seat belt buckles, free of charge. An interim letter will be mailed beginning January 25, 2019 to notify owners of the issue. A second letter will be mailed once remedy parts are available. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	C300	2019
MERCEDES BENZ	C43 AMG	2019
MERCEDES BENZ	E450	2019
MERCEDES BENZ	E53	2019
MERCEDES BENZ	S450	2019
MERCEDES BENZ	S560	2019
MERCEDES BENZ	S63 AMG	2019
MERCEDES BENZ	S65 AMG	2019
MERCEDES-MAYBACH	S560	2019
MERCEDES-MAYBACH	S650	2019

Incorrect Display of Passenger Air Bag Status

NHTSA Campaign Number: 18V838000

Manufacturer Mercedes-Benz USA, LLC.

Components AIR BAGS

Potential Number of Units Affected 104,663

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2018 C300 Cabriolet, C300 Coupe, C300 4Matic Cabriolet, C300, C300 4Matic Coupe, C300 4Matic, C43 AMG Cabriolet, C43 AMG Coupe, C63 S AMG Cabriolet, C350e Plug-In Hybrid, C63 AMG Cabriolet, C63 AMG Coupe, C63 S AMG Coupe, C63 AMG, C63 S AMG, 2018-2019 GLC300 4Matic Coupe, GLC300, GLC63 AMG Coupe, GLC300 4Matic, GLC350e Plug-In Hybrid, GLC43 AMG Coupe, GLC43 AMG, GLC63 S AMG Coupe, and GLC63 AMG vehicles equipped with Audio 20 head units and automatic child seat recognition. The status of the passenger side air bag may not display correctly.

Remedy

MBUSA will notify owners, and dealers will update the audio head unit software, free of charge. The recall is expected to begin January 2, 2019. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	C300	2018
MERCEDES BENZ	C300 4MATIC	2018
MERCEDES BENZ	C350E	2018
MERCEDES BENZ	C43 AMG	2018
MERCEDES BENZ	C63 AMG	2018
MERCEDES BENZ	C63S AMG	2018
MERCEDES BENZ	GLC300	2018-2019
MERCEDES BENZ	GLC350E	2018-2019
MERCEDES BENZ	GLC43 AMG	2018-2019
MERCEDES BENZ	GLC63 AMG	2018-2019
MERCEDES BENZ	GLC63S AMG	2018-2019

Air Bag Mounting Screw may be Loose

NHTSA Campaign Number: 18V836000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 12

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Audi A5 Sportback and 2017-2018 Audi A4 Allroad vehicles. A passenger air bag module mounting screw may not have been sufficiently tightened, possibly affecting the deployment of the air bag in the event of a crash.

Remedy

Volkswagen will notify owners, and dealers will inspect the air bag mounting screw, tightening or replacing it as necessary, free of charge. The recall is expected to begin January 26, 2019. Owners may contact Audi customer service at 1-800-253-2834. Volkswagen's number for this recall is 69Y4.

Vehicles

MAKE MODEL YEAR

AUDI	A4	2017-2018
AUDI	A5	2018

System Warning Lamps Inoperative After Restart

NHTSA Campaign Number: 18V833000

Manufacturer Automobili Lamborghini

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 1,152

Summary

Automobili Lamborghini (Lamborghini) is recalling certain 2011-2014 Gallardo Coupe and Gallardo Spyder vehicles. The Engine Control Unit (ECU) software may erase trouble codes after the ignition is turned off, not illuminating warning lamps and preventing drivers from being warned of safety system problems the next time that they are driving.

Remedy

Lamborghini will notify owners, and dealers will reflash the engine software with the appropriate procedure, free of charge. The recall is expected to begin December 14, 2018. Owners may contact Lamborghini customer service at 1-866-681-6276. Lamborghini's number for this recall is L61XR0118.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

LAMBORGHINI	GALLARDO	2011-2014
-------------	----------	-----------