



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

December 3, 2018

### [Driver's Frontal Air Bag May Deploy Unexpectedly](#)

**NHTSA Campaign Number:** 18V787000

**Manufacturer** Daimler Trucks North America LLC

**Components** AIR BAGS

**Potential Number of Units Affected** 2,894

#### Summary

Daimler Trucks North America LLC (DTNA) is recalling certain 2017-2019 Freightliner Cascadia vehicles. The driver's frontal air bag may deploy unexpectedly.

#### Remedy

DTNA will notify owners, and dealers will modify the wiring leading to the steering wheel clockspring and ensure that it is properly grounded, free of charge. The recall is expected to begin January 9, 2019. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL800.

#### Vehicle

MAKE	MODEL	YEAR
------	-------	------

FREIGHTLINER	CASCADIA	2017-2019
--------------	----------	-----------

## No GPS Location in the Event of a Crash

**NHTSA Campaign Number:** 18V800000

**Manufacturer** Volvo Car USA LLC

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 17,548

### **Summary**

Volvo Car USA LLC (Volvo) is recalling certain 2017-2019 Volvo XC90, S90, V60, V60 Cross Country, V90, XC40, XC60, and V90 Cross Country vehicles. The Actia Nordic AB software installed in the Vehicle Connectivity Module (VCM) may have an error causing the Telematics and Driver Support Systems to function improperly. As a result, the GPS will not provide location information to emergency personnel in the event of an emergency.

### **Remedy**

Volvo will notify owners, and dealers will correct the software, free of charge. The recall is expected to begin January 7, 2019. Owners may contact Volvo customer service at 1-800-458-1552. Volvo's number for this recall is R39917.

### **Vehicles**

#### **MAKE MODEL YEAR**

VOLVO S90	2017-2019
VOLVO V60	2017-2019
VOLVO V60CC	2017-2019
VOLVO V90	2017-2019
VOLVO V90CC	2017-2019
VOLVO XC40	2017-2019
VOLVO XC60	2017-2019
VOLVO XC90	2017-2019

## Incorrectly Welded Rear Seat Guide Sleeves

**NHTSA Campaign Number:** 18V803000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** SEATS

**Potential Number of Units Affected** 169

### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Volkswagen e-Golf and Golf R vehicles, and Audi A3 Sedan and RS3 vehicles. The Lear rear seat frame head restraint guide sleeves may be incorrectly welded to the seat frame.

### **Remedy**

Volkswagen and Audi will notify their owners, and dealers will inspect the guide sleeves for incorrect welds, replacing the rear seat frame, as necessary, free of charge. The recall is expected to begin January 11, 2019. Owners may contact Volkswagen customer service at 1-800-893-5298 or Audi customer service at 1-800-253-2834. Volkswagen's numbers for this recall are 72H8 (VW) and 72H9(Audi).

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
AUDI	A3	2018
AUDI	RS3	2018
VOLKSWAGEN	E-GOLF	2018
VOLKSWAGEN	GOLF R	2018

## **Seats are Missing J-Channel Reinforcement Brackets**

**NHTSA Campaign Number:** 18V805000

**Manufacturer** Ford Motor Company

**Components** SEATS

**Potential Number of Units Affected** 34,946

### **Summary**

Ford Motor Company (Ford) is recalling certain 2018 Lincoln Navigator, and Ford Expedition vehicles. The Magna second row center seat track assemblies may be missing one or both of the J-Channel reinforcement brackets, possibly allowing the seat to move in the event of a crash.

### **Remedy**

Ford will notify owners, and dealers will inspect the second row center seat for any missing J-channel reinforcement brackets, replacing the center seat frame assembly as necessary, free of charge. The recall is expected to begin December 17, 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S37

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
FORD	EXPEDITION	2018
LINCOLN	NAVIGATOR	2018

## Driver Air Bag Module Plastic Cover may Detach

**NHTSA Campaign Number:** 18V806000

**Manufacturer** Ford Motor Company

**Components** AIR BAGS

**Potential Number of Units Affected** 268

### **Summary**

Ford Motor Company (Ford) is recalling certain 2019 Lincoln Nautilus vehicles that are not equipped with Adaptive Front Steering. The Autoliv plastic cover on the driver frontal air bag module may detach during air bag deployment.

### **Remedy**

Ford will notify owners, and dealers will replace the driver air bag module, free of charge. The recall is expected to begin in November 2018. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 18S38.

### **Vehicle**

**MAKE    MODEL    YEAR**

LINCOLN NAUTILUS 2019