



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

March 25, 2019

Turn-Signals Will Not Self-Cancel After Turn

NHTSA Campaign Number: 19V117000

Manufacturer General Motors LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 5

Summary

General Motors LLC (GM) is recalling certain 2019 Cadillac CT6 vehicles. Rotation of the steering wheel will not automatically cancel the turn-signals from flashing. As such, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices and Associated Equipment."

Remedy

GM has notified owners, and dealers will replace the turn-signal switch. The recall began March 11, 2019. Owners may contact Cadillac customer service at 1-800-458-8006. The Cadillac number for this recall is N182207090.

Vehicle

MAKE MODEL YEAR

CADILLAC CT6 2019

No Visual Warning of Brake Pad Wear/FMVSS 135

NHTSA Campaign Number: 19V115000

Manufacturer Porsche Cars North America, Inc.

Components ELECTRICAL SYSTEM, SERVICE BRAKES

Potential Number of Units Affected 14,110

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2018 Panamera 4 Executive, Panamera 4S Sport Turismo, Panamera 4 Hybrid, Panamera 4 Hybrid Executive, Panamera 4 Hybrid Sport Turismo, Panamera Turbo Sport Turismo, Panamera Turbo S Hybrid Executive, Panamera Turbo S Hybrid, Panamera 4 Sport Turismo and Panamera Turbo S Hybrid Sport Turismo vehicles, 2017-2018 Panamera, Panamera 4, Panamera Turbo Executive, Panamera 4S, Panamera Turbo and Panamera 4S Executive vehicles and 2019 Cayenne S and Cayenne vehicles. The instrument cluster may not provide a visual warning when the brake pads are worn out. As a result, these vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 135, "Light vehicle brake systems."

Remedy

Porsche will notify owners, and dealers will update the instrument cluster software, free of charge. The recall is expected to begin April 21, 2019. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AKA1/AKA0.

Vehicles

| MAKE | MODEL | YEAR |
|-------------|---------------------------------------|-------------|
| PORSCHE | CAYENNE | 2019 |
| PORSCHE | CAYENNE S | 2019 |
| PORSCHE | PANAMERA | 2017-2018 |
| PORSCHE | PANAMERA 4 | 2017-2018 |
| PORSCHE | PANAMERA 4 EXECUTIVE | 2018 |
| PORSCHE | PANAMERA 4 HYBRID | 2018 |
| PORSCHE | PANAMERA 4 HYBRID EXECUTIVE | 2018 |
| PORSCHE | PANAMERA 4 HYBRID SPORT TURISMO | 2018 |
| PORSCHE | PANAMERA 4 SPORT TURISMO | 2018 |
| PORSCHE | PANAMERA 4S | 2017-2018 |
| PORSCHE | PANAMERA 4S EXECUTIVE | 2017-2018 |
| PORSCHE | PANAMERA 4S SPORT TURISMO | 2018 |
| PORSCHE | PANAMERA TURBO | 2017-2018 |
| PORSCHE | PANAMERA TURBO EXECUTIVE | 2017-2018 |
| PORSCHE | PANAMERA TURBO S HYBRID | 2018 |
| PORSCHE | PANAMERA TURBO S HYBRID EXECUTIVE | 2018 |
| PORSCHE | PANAMERA TURBO S HYBRID SPORT TURISMO | 2018 |
| PORSCHE | PANAMERA TURBO SPORT TURISMO | 2018 |

Delayed Camera Display/FMVSS 111

NHTSA Campaign Number: 19V111000

Manufacturer Porsche Cars North America, Inc.

Components VISIBILITY, BACK OVER PREVENTION

Potential Number of Units Affected 98

Summary

Porsche Cars North America, Inc (Porsche) is recalling certain 2019 Cayenne and Cayenne S vehicles. A software failure may cause the rearview camera image display to be delayed in responding. As such these vehicles fail to comply to Federal Motor Safety Standard (FMVSS) number 111, "Rearview Mirrors."

Remedy

Porsche will notify owners, and dealers will update the related software, free of charge. The recall is expected to begin April 21, 2019. Owners may contact Porsche customer service at 1-800-767-7243. Porsche's number for this recall is AKA0.

Vehicle

MAKE MODEL YEAR

PORSCHE CAYENNE 2019

Incorrect Driver Frontal Air bag Installed

NHTSA Campaign Number: 19V110000

Manufacturer Volkswagen Group of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 4

Summary

Volkswagen Group of America (Volkswagen) is recalling certain 2019 Jetta vehicles. An incorrect driver frontal airbag may have been installed during a service/repair visit.

Remedy

Volkswagen will notify owners, and dealers will replace the driver frontal air bag with the correct part, free of charge. The recall is expected to begin April 19, 2019. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69Y7.

Vehicle

MAKE MODEL YEAR

VOLKSWAGEN JETTA 2019

Driver's Seat and Seat Belt Bolts may be Loose

NHTSA Campaign Number: 19V096000

Manufacturer BMW of North America, LLC

Components SEAT BELTS, SEATS

Potential Number of Units Affected 68

Summary

BMW of North America, LLC (BMW) is recalling certain 2019 X5 xDrive40i and xDrive50i vehicles. The attachment bolts for the driver's seat and/or seat belt may not have been properly tightened.

Remedy

BMW will notify owners, and dealers will inspect the attachment bolts for the driver's seat and seat belt, and torque them to the correct specifications, as necessary, free of charge. The recall is expected to begin April 5, 2019. Owners may contact BMW customer service at 1-800-525-7417.

Vehicle

MAKE MODEL YEAR

BMW X5 2019

Rear Center Headrests May Detach in a Crash

NHTSA Campaign Number: 19V095000

Manufacturer Volkswagen Group of America, Inc.

Components SEATS

Potential Number of Units Affected 3,326

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2018 Audi A3 sedan and RS3 vehicles. The latching pins for the center rear seat head restraint may be missing.

Remedy

Audi has notified owners, and dealers will inspect the head restraints, replacing any that are missing pins, free of charge. The recall began on March 7, 2019. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 72I8.

Vehicles

MAKE MODEL YEAR

| | | |
|------|-----|------|
| AUDI | A3 | 2018 |
| AUDI | RS3 | 2018 |

No Visual Warning of Brake Failure/FMVSS 135;101

NHTSA Campaign Number: 19V094000

Manufacturer Volkswagen Group of America, Inc.

Components ELECTRICAL SYSTEM, SERVICE BRAKES

Potential Number of Units Affected 4,064

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019 Beetle and Beetle Convertible vehicles. The instrument cluster may not provide a visual warning when a brake system failure is detected. As a result, the vehicles fail to comply with Federal Motor Vehicle Safety Standard (FMVSS) number 135, "Light vehicle brake systems" and number 101, "Controls and displays."

Remedy

Volkswagen will notify owners, and dealers will update the instrument cluster software, free of charge. The recall began March 7, 2019. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 90L8.

Vehicle

| MAKE | MODEL YEAR |
|------|------------|
|------|------------|

| | |
|-------------------|------|
| VOLKSWAGEN BEETLE | 2019 |
|-------------------|------|