



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

May 13, 2019

### [Instrument Panel may Affect Air Bag Deployment](#)

**NHTSA Campaign Number:** 19V291000

**Manufacturer** BMW of North America, LLC

**Components** ELECTRICAL SYSTEM, AIR BAGS

**Potential Number of Units Affected** 50

#### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2019 X3 sDrive30i, X3 xDrive30i, X3 M40i, and X4 M40i vehicles. The instrument panel assembly may have been improperly manufactured, possibly affecting the deployment of the passenger's frontal air bag.

#### **Remedy**

BMW will notify owners, and dealers will replace the instrument panel assembly, free of charge. The recall is expected to begin June 3, 2019. Owners may contact BMW customer service at 1-800-525-7417.

#### **Vehicles**

##### **MAKE MODEL YEAR**

BMW	X3	2019
BMW	X4	2019

## Electrical Power May Shutdown

**NHTSA Campaign Number:** 19V310000

**Manufacturer** BMW of North America, LLC

**Components** ELECTRICAL SYSTEM, HYBRID PROPULSION SYSTEM

**Potential Number of Units Affected** 159

### **Summary**

BMW of North America, LLC (BMW) is recalling certain 2018 i3 BEV and i3 REx hybrid electric vehicles. A circuit board problem within the Electric Motor Electronics (EME) module may shutdown the supply of high voltage electrical power.

### **Remedy**

BMW will notify owners, and dealers will replace the EME module, free of charge. The recall is expected to begin June 7, 2019. Owners may contact BMW customer service at 1-800-525-7417.

### **Vehicle**

#### **MAKE MODEL YEAR**

BMW I3 2018

## Pedal Plate May Bend, Impairing Brake Pedal Use

**NHTSA Campaign Number:** 19V314000

**Manufacturer** Mercedes-Benz USA, LLC.

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 1,051

### **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2019 A220 and A220 4MATIC vehicles. Due to improper welding, the pedal plate may bend, impairing the operation of the brake pedal.

### **Remedy**

MBUSA will notify owners, and dealers will inspect the welding of the brake pedal, replacing it as necessary, free of charge. The recall is expected to begin June 19, 2019. Owners may contact MBUSA customer service at 1-800-367-6372.

**Vehicle**

**MAKE            MODEL YEAR**

MERCEDES BENZ A220    2019