



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

June 10, 2019

ORC May Malfunction and Disable Safety Functions

NHTSA Campaign Number: 19V407000

Manufacturer Chrysler (FCA US LLC)

Components AIR BAGS, SEAT BELTS

Potential Number of Units Affected 295,981

Summary

Chrysler (FCA US LLC) is recalling certain 2019-2020 Ram 1500 vehicles. The flash memory of the Occupant Restraint Controller (ORC) may become corrupted, disabling the vehicle's air bags and seat belt pretensioners.

Remedy

Chrysler will notify owners, and dealers will reprogram the ORC or replace it as necessary, free of charge. The recall is expected to begin July 20, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's numbers for this recall are V61 and V71.

Vehicle

MAKE MODEL YEAR

RAM 1500 2019-2020

Incorrect Air Bag and Seat Belt Indicators

NHTSA Campaign Number: 19V363000

Manufacturer Mazda North American Operations

Components SEAT BELTS, ELECTRICAL SYSTEM

Potential Number of Units Affected 17,016

Summary

Mazda North American Operations (Mazda) is recalling certain 2019 Mazda3 vehicles. Due to incorrect programming, the passenger air bag deactivation indicator light may erroneously turn off although the passenger air bag is deactivated. In addition, the seat belt status indicators for both the front passenger seat and/or rear seats may erroneously turn off although the front passenger and/or rear seat belts are unfastened.

Remedy

Mazda will notify owners, and dealers will replace the passenger air bag/seat belt status indicator assembly, free of charge. The recall is expected to begin July 13, 2019. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 3319E.

Vehicle

MAKE MODEL YEAR

MAZDA MAZDA3 2019

Occupant Detection System May Misclassify

NHTSA Campaign Number: 19V343000

Manufacturer Suzuki Motor of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 21,052

Summary

Suzuki Motor of America, Inc. (Suzuki) is recalling 2010-2013 Kizashi vehicles. The front passenger seat Occupant Classification System (OCS) may misclassify an adult occupant as child and deactivate the front air bag.

Remedy

The remedy for this recall is still under development. The manufacturer has not yet provided a notification schedule. Owners may contact Suzuki customer service at 1-800-934-0934. Suzuki's number for this recall is C5.

Vehicle

MAKE MODEL YEAR

SUZUKI KIZASHI 2010-2013

Regenerative Brake System May Fail/FMVSS 135

NHTSA Campaign Number: 19V351000

Manufacturer Jaguar Land Rover North America, LLC

Components SERVICE BRAKES

Potential Number of Units Affected 3,083

Summary

Jaguar Land Rover North America, LLC (Jaguar) is recalling certain 2019-2020 I-PACE vehicles. If the electrical regenerative brake system fails, there will be an increased delay between when the driver brakes and when the vehicle decelerates. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 135, "Light Vehicle Brake Systems."

Remedy

Jaguar will notify owners, and dealers will update the software to reduce the delay, free of charge. The recall is expected to begin July 1, 2019. Owners may contact Jaguar customer service at 1-800-637-6837. Jaguar's number for this recall is H213.

Vehicle

MAKE MODEL YEAR

JAGUAR I-PACE 2019-2020

