

NHTSA Recalls of Interest July 8, 2019

Incorrect ORC Calibration

NHTSA Campaign Number: 19V438000

Manufacturer Chrysler (FCA US LLC)

Components AIR BAGS

Potential Number of Units Affected 745

Summary

Chrysler (FCA US LLC) is recalling certain 2019 Jeep Renegade vehicles equipped with the Upland trim package. The Occupant Restraint Controller (ORC) may have been incorrectly calibrated.

Remedy

Chrysler will notify owners, and dealers will reprogram the ORC. The recall is expected to begin July 31, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V73.

Vehicle

MAKE MODEL YEAR

JEEP RENEGADE 2019

Back Up Camera Display Image may be Reversed

NHTSA Campaign Number: 19V428000

Manufacturer Unicell Body Company Inc.

Components EQUIPMENT

Potential Number of Units Affected 325

Summary

Unicell Body Company Inc. (Unicell) is recalling certain 2017-2019 Chevrolet Express and GMC Savanna, 2018-2019 Hino 155, Ford Econoline and Transit and Isuzu NPR, and 2018 Ram ProMaster-based vehicles equipped with ASA Electronics Voyager monitors used to display the back-up camera image. The affected monitors may revert back to the factory default settings which may cause the camera image to be reversed.

Remedy

Unicell will work with ASA Electronics to notify owners and offer a remedy, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact ASA Electronics customer service 1-800-384-4400 or Unicell at 1-716-853-8628.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	EXPRESS	2017-2019
FORD	ECONOLINE	2018-2019
GMC	SAVANA	2017-2019
HINO	155	2018-2019
ISUZU	NPR	2018-2019
RAM	PROMASTER	2018

Driver Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 19V499000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 13,577

Summary

Honda (American Honda Motor Co.) is recalling certain 2003 Acura 3.2CL, 2002-2003 3.2TL, 2003-2006 MDX, 2001-2007 Honda Accord, 2001-2005 Civic, 2003-2005 Civic Hybrid, 2001-2005 Civic GX NGV, 2002-2006 CR-V, 2003-2011 Element, 2002-2004 Odyssey, 2003-2008 Pilot and 2006 Ridgeline vehicles.

These vehicles are equipped with driver frontal air bag inflators assembled as a recall remedy part or replacement service part, that may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the driver frontal air bag inflator, free of charge. The recall is expected to begin August 12, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are Q5A and Y58.

Vehicles

MAKE	MODEL	YEAR
ACURA	CL	2003
ACURA	MDX	2003-2006
ACURA	TL	2002-2003
HONDA	ACCORD	2001-2007
HONDA	CIVIC	2001-2005
HONDA	CIVIC GX	2001-2005
HONDA	CIVIC HYBRID	2003-2005
HONDA	CR-V	2002-2006
HONDA	ELEMENT	2003-2011
HONDA	ODYSSEY	2002-2004
HONDA	PILOT	2003-2008
HONDA	RIDGELINE	2006

Driver Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 19V500000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 1,567

Summary

Honda (American Honda Motor Co.) is recalling certain 2013 Acura ILX, 2015 RDX, 2005-2010 and 2012 RL, 2009-2014 TL, 2010 and 2012 ZDX, 2007-2011 CR-V, 2011-2013 and 2015 CR-Z, 2009-2013 Fit, 2013 Fit EV, 2010-2011 and 2013 Insight and 2007-2014 Ridgeline vehicles.

These vehicles are equipped with driver frontal air bag inflators assembled as a recall remedy part or replacement service part, that may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the driver frontal air bag inflator, free of charge. The recall is expected to begin August 12, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are S5B and W59.

Vehicles

MAKE	MODEL	YEAR
ACURA	ILX	2013
ACURA	RDX	2015
ACURA	RL	2005-2010, 2012
ACURA	TL	2009-2014
ACURA	ZDX	2010, 2012
HONDA	CR-V	2007-2011
HONDA	CR-Z	2011-2013, 2015
HONDA	FIT	2009-2013
HONDA	INSIGHT	2010-2011, 2013
HONDA	RIDGELINE	2007-2014

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 19V501000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 1,657,813

Summary

Honda (American Honda Motor Co.) is recalling certain 2003-2006 Acura MDX, 2005-2012 RL, 2003-2007 Honda Accord, 2001-2005 Civic, 2003-2005 Civic Hybrid, 2001-2005 Civic GX NGV, 2002-2006 CR-V, 2003-2011 Element, 2007-2008 Fit, 2002-2004 Odyssey, 2003-2008 Pilot, and 2006-2014 Ridgeline vehicles.

The vehicles are equipped with passenger frontal air bag inflators assembled as a recall remedy part or replacement service part, that may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the passenger frontal airbag inflator, free of charge. The recall is expected to begin August 12, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are E5D and X5C.

Vehicles

MAKE	MODEL	YEAR
ACURA	MDX	2003-2006
ACURA	RL	2005-2012
HONDA	ACCORD	2003-2007
HONDA	CIVIC	2001-2005
HONDA	CIVIC GX	2001-2005
HONDA	CIVIC HYBRID	2003-2005
HONDA	CR-V	2002-2006
HONDA	ELEMENT	2003-2011
HONDA	FIT	2007-2008
HONDA	ODYSSEY	2002-2004
HONDA	PILOT	2003-2008
HONDA	RIDGELINE	2006-2014

Passenger Frontal Air Bag Inflator May Explode

NHTSA Campaign Number: 19V502000

Manufacturer Honda (American Honda Motor Co.)

Components AIR BAGS

Potential Number of Units Affected 9,566

Summary

Honda (American Honda Motor Co.) is recalling certain 2009-2014 Acura TSX, 2011-2014 TSX Sport Wagon, 2010-2013 ZDX, 2008-2012 Honda Accord, 2010-2011 Accord Crosstour, 2006-2011 Civic and Civic Hybrid, 2008-2010 Civic GX NGV, 2012-2015 Crosstour, 2007-2011 CR-V, 2009-2013 Fit, 2014 Fit EV, 2010-2014 Insight, and 2009-2015 Pilot vehicles.

The vehicles are equipped with passenger frontal air bag inflators assembled as a recall remedy part or replacement service part, that may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy

Honda will notify owners, and dealers will replace the passenger frontal air bag inflator, free of charge. The recall is expected to begin August 12, 2019. Owners may contact Honda customer service at 1-888-234-2138. Honda's numbers for this recall are F5F and Q5E.

Vehicles

YEAR
2009-2014
2011-2014
2010-2013
2008-2012
R 2010-2011
2006-2011
2008-2010
2006-2011
2007-2011
2012-2015
2009-2013
2014
2010-2014
2009-2015