



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

August 12, 2019

Front Seatbacks May Fold Unexpectedly

NHTSA Campaign Number: 19V563000

Manufacturer BMW of North America, LLC

Components SEATS

Potential Number of Units Affected 20

Summary

BMW of North America, LLC (BMW) is recalling certain 2018-2019 X3 sDrive30i, xDrive30i and M40i and 2019 X4 xDrive30i and M40i vehicles. The front seatback frames may have been improperly welded, allowing the seatback to unexpectedly fold forward or rearward.

Remedy

BMW will notify owners, and dealers will replace the front seats, free of charge. The recall is expected to begin September 23, 2019. Owners may contact BMW customer service 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

BMW	X3	2018-2019
BMW	X4	2019

Loss of Stability Control, Brake Assist/FMVSS 126

NHTSA Campaign Number: 19V544000

Manufacturer Toyota Motor Engineering & Manufacturing

Components ELECTRONIC STABILITY CONTROL, SERVICE BRAKES

Potential Number of Units Affected 6,925

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2019 Lexus LS500, LC500, ES300h, UX250h, LS500h, Toyota Prius, RAV4 HV, 2019-2020 Toyota Prius Prime, and 2020 Corolla HV vehicles. The brake booster pump may fail causing a deactivation of the Vehicle Stability Control system and a loss of braking assist. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 126, "Electronic Stability Control Systems."

Remedy

Toyota will notify owners, and dealers will inspect and, if necessary, replace the brake booster pump, free of charge. The recall is expected to begin September 9, 2019. Toyota owners may contact Toyota customer service at 1-888-270-9371 and Lexus owners may contact Lexus customer service at 1-800-255-3987. Toyota's numbers for this recall are K1L/K0L. Lexus' numbers for this recall are K2F/KLF.

Vehicles

MAKE	MODEL	YEAR
LEXUS	ES300H	2019
LEXUS	LC500	2019
LEXUS	LS500	2019
LEXUS	LS500 H	2019
LEXUS	UX250 HYBRID	2019
TOYOTA	COROLLA HYBRID	2020
TOYOTA	PRIUS	2019
TOYOTA	PRIUS PRIME	2019-2020
TOYOTA	RAV4 HYBRID	2019

Fuel Gauge may Read Higher than Actual Level

NHTSA Campaign Number: 19V551000

Manufacturer Chrysler (FCA US LLC)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 21,915

Summary

Alfa Romeo (FCA US LLC) is recalling certain 2018-2019 Giulia and Stelvio vehicles. The Body Control Module (BCM) may indicate an inaccurate fuel level that displays higher than the actual amount.

Remedy

Alfa Romeo will notify owners, and dealers will update the BCM software, free of charge. The recall is expected to begin September 13, 2019. Owners may contact Alfa Romeo customer service at 1-800-853-1403. Alfa Romeo's number for this recall is V84.

Vehicles

MAKE	MODEL	YEAR
ALFA ROMEO	GIULIA	2018-2019
ALFA ROMEO	STELVIO	2018-2019

Driver Warnings May Not Illuminate/FMVSS 101

NHTSA Campaign Number: 19V556000

Manufacturer Chrysler (FCA US LLC)

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 1

Summary

Chrysler (FCA US LLC) is recalling one 2019 Ram 1500 vehicle. The instrument cluster may not properly illuminate driver warnings. As such, this vehicle fails to conform with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 101, "Control and Displays."

Remedy

Chrysler will notify the owner, and a dealer will replace the instrument cluster, free of charge. The recall is expected to begin September 13, 2019. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V83.

Vehicle

MAKE MODEL YEAR

RAM 1500 2019

Rearview Mirror Glass May Detach From Housing

NHTSA Campaign Number: 19V558000

Manufacturer Mazda North American Operations

Components VISIBILITY

Potential Number of Units Affected 22,571

Summary

Mazda North American Operations (Mazda) is recalling certain 2019 Mazda3 vehicles equipped with manual dimming mirrors. The adhesive between the interior rearview mirror and the housing may not be properly bonded, allowing the mirror to detach from the housing. Note: Vehicles equipped with auto dimming mirrors are not affected by this recall.

Remedy

Mazda will notify owners, and dealers will replace the interior rearview mirror assembly, free of charge. The recall is expected to begin August 30, 2019. Owners may contact Mazda customer service at 1-800-222-5500, option 4. Mazda's number for this recall is 3919G.

Vehicle

MAKE MODEL YEAR

MAZDA MAZDA3 2019