



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

August 19, 2019

### Improperly Calibrated OCS

**NHTSA Campaign Number:** 19V567000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** AIR BAGS

**Potential Number of Units Affected** 680

#### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2019 Camry vehicles. The Occupant Classification System (OCS) may have been improperly calibrated, which may prevent the proper deployment of the front passenger air bag and knee air bag, in the event of a crash. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

#### **Remedy**

Toyota will notify owners, and dealers will recalibrate the OCS, free of charge. The recall is expected to begin August 15, 2019. Owners may contact Toyota customer service at 1-888-270-9371. Toyota's number for this recall is KOM.

#### **Vehicle**

**MAKE MODEL YEAR**

TOYOTA CAMRY 2019

## Knee Air Bags Cushions may not Properly Inflate

**NHTSA Campaign Number:** 19V562000

**Manufacturer** Pierce Manufacturing

**Components** AIR BAGS

**Potential Number of Units Affected** 174

### **Summary**

Pierce Manufacturing (Pierce) is recalling certain 2019 Arrow XT, Dash, Enforcer, Impel, Quantum, and Velocity vehicles. Due to improper manufacturing, the passenger-side knee air bag (KAB) may not properly inflate during a deployment event.

### **Remedy**

Pierce will notify owners, and dealers will replace the KAB assembly, free of charge. The recall is expected to begin August 2019. Owners may contact Pierce customer service at 1-888-974-3723.

### **Vehicles**

**MAKE MODEL YEAR**

PIERCE ARROW XT 2019  
PIERCE DASH 2019  
PIERCE ENFORCER 2019  
PIERCE IMPEL 2019  
PIERCE QUANTUM 2019  
PIERCE VELOCITY 2019