

NHTSA Recalls of Interest October 14, 2019

No Back-Up Camera Display Image/FMVSS 111

NHTSA Campaign Number: 19V684000

Manufacturer BMW of North America, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 257,473

Summary

BMW of North America, LLC (BMW) is recalling certain 2018 540d, 2018-2020 530i, 530i xDrive, 540i, 540i xDrive, M550i xDrive, M5, 530e, 530e xDrive, X3 sDrive, X3 xDrive, X3 M40i, X3 M, and 2019-2020 X4 xDrive, X4 M40i, X4 M, X7 xDrive, X7 M50i, 740Li, 740Li xDrive, 750Li, 750Li xDrive, 8 Series Convertible and Coupe 840i, 840i xDrive, M850i xDrive, X5 sDrive, X5 xDrive, X5 M50i, X6 xDrive, X6 M50i, 330i, 330i xDrive, M340i, M340i xDrive, Z4 sDrive, Z4 M40i, 740Le xDrive and 745Le xDrive, 2018-2019 640i xDrive Gran Turismo and Rolls-Royce Phantom, 2019 M850i xDrive Gran Coupe and Rolls-Royce Cullinan and 2020 Toyota Supra vehicles.

The back-up camera and display settings can be adjusted such that the rear view image is no longer visible and the system will retain that setting the next time the vehicle is placed in reverse. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rearview Mirrors."

Remedy

BMW will notify owners, and dealers will update the back-up camera software, free of charge. The recall is expected to begin November 19, 2019. Owners may contact BMW customer service at 1-800-525-7417 or Rolls-Royce at 1-877-877-3735. Toyota owners may contact Toyota customer service at 1-888-270-9371.

Vehicles

MAKE	MODEL	YEAR
DMM	2201	2010 2020
BMW	330I	2019-2020
BMW	530E	2018-2020
BMW	530I	2018-2020
BMW	540D	2018
BMW	540I	2018-2020
BMW	640I	2018-2019
BMW	740LE	2019-2020
BMW	740LI	2019-2020
BMW	745LE	2019-2020
BMW	750LI	2019-2020
BMW	840I	2019-2020
BMW	M340I	2019-2020
BMW	M5	2018-2020
BMW	M550I	2018-2020
BMW	M850I	2019-2020
BMW	X3	2018-2020
BMW	X4	2019-2020
BMW	X5	2019-2020
BMW	X6	2019-2020
BMW	X7	2019-2020
BMW	Z4	2019-2020
ROLLS-ROYCE	CULLINAN	2019
ROLLS-ROYCE	PHANTOM	2018-2019
ΤΟΥΟΤΑ	SUPRA	2020

Airbag System may be Deactivated

NHTSA Campaign Number: 19V695000

Manufacturer Daimler Vans USA, LLC

Components AIR BAGS

Potential Number of Units Affected 1,232

Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2018-2019 Mercedes-Benz and Freightliner Sprinter vehicles. The airbag systems may not have been activated after vehicle production. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

Remedy

DVUSA will notify owners, and dealers will inspect the vehicles to determine if the airbag systems have been activated, correcting them as necessary, free of charge. The recall is expected to begin November 18, 2019. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3AIRIGEL.

Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	SPRINTER 1500	2018-2019
FREIGHTLINER	SPRINTER 2500	
FREIGHTLINER	SPRINTER 3500	2018-2019
FREIGHTLINER	SPRINTER 4500	2018-2019
MERCEDES BENZ	SPRINTER 1500	2018-2019
MERCEDES BENZ	SPRINTER 2500	2018-2019
MERCEDES BENZ	SPRINTER 3500	2018-2019
MERCEDES BENZ	SPRINTER 4500	2018-2019

Occupant Detection System May Deactivate Airbag

NHTSA Campaign Number: 19V701000

Manufacturer Subaru of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 366,282

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2015-2018 Forester vehicles equipped with heated seats. An electrical connection in the front passenger seat for the Occupant Detection System (ODS) may loosen.

Remedy

Subaru will notify owners, and dealers will inspect and, as necessary, replace the ODS sensor mat harness, free of charge. Parts are not currently available. Owners will be notified of the recall beginning November 29, 2019, and will receive a second notice when remedy parts are available. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WUM-98.

Vehicle

MAKE MODEL YEAR

SUBARU FORESTER 2015-2018

Incorrect Airbag Information In Guide/FMVSS 208

NHTSA Campaign Number: 19V694000

Manufacturer Honda (American Honda Motor Co.)

Components EQUIPMENT

Potential Number of Units Affected 336,468

Summary

Honda (American Honda Motor Co.) is recalling certain 2019 CR-V vehicles. The owner's guide provides incorrectly describes when the "Passenger Airbag Off" indicator should illuminate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 208, "Occupant Crash Protection."

Remedy

Honda will notify owners and provide a sticker with the correct information to be added to the owner's guide, free of charge. The recall is expected to begin November 15, 2019. Owner's may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is X6G.

Vehicle

MAKE MODEL YEAR

HONDA CR-V 2019