

NHTSA Recalls of Interest

October 21, 2019

Steering Wheel Airbag Inflator May Explode

NHTSA Campaign Number: 19V698000

Manufacturer BMW of North America, LLC

Components AIR BAGS

Potential Number of Units Affected 3,924

Summary

BMW of North America, LLC (BMW) is recalling certain 2000-2002 325i and 325xi Sedan, and 323Ci, 325Ci, and 330Ci Convertible vehicles. This recall affects certain vehicles that may have had a driver-side air bag module installed as replacement equipment such as after a vehicle crash necessitating replacement of the original air bag, or as a remedy part for a prior recall. The frontal air bag inflator may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

Remedy

BMW will notify owners, and dealers will inspect and, as necessary, replace the driver's air bag module, free of charge. The recall is expected to begin November 25, 2019. Owners may contact BMW customer service at 1-800-525-7417. Note: This recall is an expansion of previous recalls, numbers 17V-047 and 19V-015.

Vehicles

MAKE MODEL YEAR

BMW	323	2000-2002
BMW	325	2000-2002
BMW	330	2000-2002

Brake Calipers May Drag

NHTSA Campaign Number: 19V704000

Manufacturer General Motors LLC

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 166

Summary

General Motors LLC (GM) is recalling certain 2020 Chevrolet Equinox vehicles. The rear brake calipers may have been produced with an incorrect lubricant, potentially causing the rubber seals to swell and the brakes to drag.

Remedy

GM will notify owners, and dealers will replace the rear brake calipers, including the brake hose gasket, brake fluid and wheel to hub lubricant, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-630-2438. GM's number for this recall is N192270920.

Vehicle

MAKE MODEL YEAR

CHEVROLET EQUINOX 2020