



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

November 25, 2019

### Fire after Seat Belt Pretensioner Deployment

**NHTSA Campaign Number:** 19V814000

**Manufacturer** General Motors LLC

**Components** SEAT BELTS

**Potential Number of Units Affected** 556,399

#### **Summary**

General Motors LLC (GM) is recalling certain 2019-2020 Chevrolet Silverado 1500 and GMC Sierra 1500, and 2020 Silverado 2500, Silverado 3500, Sierra 2500, and Sierra 3500 vehicles equipped with carpet floor covering. When the front seat belt pretensioners deploy, hot gas may vent through an opening in the pretensioner bracket, possibly igniting the carpet.

#### **Remedy**

GM will notify owners, and dealers will close off the opening in the pretensioner bracket, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-888-988-7267. GM's number for this recall is N192270600.

## Vehicles

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO 1500	2019-2020
CHEVROLET	SILVERADO 2500	2020
CHEVROLET	SILVERADO 3500	2020
GMC	SIERRA 1500	2019-2020
GMC	SIERRA 2500	2020
GMC	SIERRA 3500	2020

## Seat Belt Webbing May Detach From Anchor

**NHTSA Campaign Number:** 19V766000

**Manufacturer** Ford Motor Company

**Components** SEAT BELTS

**Potential Number of Units Affected** 366

### Summary

Ford Motor Company (Ford) is recalling certain 2019 Edge vehicles. The driver-side seat belt pretensioner anchor may have been improperly crimped, possibly resulting in the seat belt webbing detaching from the anchor in the event of a crash.

### Remedy

Ford has notified owners, and dealers will inspect and, if necessary, replace the driver's side pretensioner assembly, free of charge. The recall began November 12, 2019. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 19S37.

### Vehicle

**MAKE MODEL YEAR**

FORD EDGE 2019

## System Interprets Seat Belts as being Unlatched

**NHTSA Campaign Number:** 19V788000

**Manufacturer** Mercedes-Benz USA, LLC.

**Components** SEAT BELTS

**Potential Number of Units Affected** 29,679

### **Summary**

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2018 E400 Wagon 4MATIC, E400 4MATIC, E43 AMG 4MATIC, 2018-2019 E63S AMG 4MATIC Wagon, E63 AMG 4MATIC Wagon, E300, E300 4MATIC, GLC63S Coupe AMG 4MATIC, 2019 CLS450, CLS450 4MATIC, CLS53 AMG 4MATIC, E450 Wagon, E53 AMG 4MATIC, GLC300, GLC63 AMG Coupe 4MATIC, G550 4MATIC, G63 AMG, GLC300 Coupe 4MATIC, GLC300 4MATIC, GLC350e 4MATIC, GLC43 AMG Coupe 4MATIC, GLC43 AMG 4MATIC, GLC63 AMG 4MATIC, GT63 AMG four-door 4MATIC, and GT63S AMG four-door 4MATIC vehicles. Although correctly fastened, the front seat belts may be inaccurately detected as being unfastened, which may cause the electric PRE-SAFE®-function and the pretensioner to be deactivated.

### **Remedy**

MBUSA will notify owners, and dealers will inspect the front seat belt buckles, replacing them as necessary, free of charge. The recall is expected to begin December 31, 2019. Owners may contact MBUSA customer service at 1-800-367-6372.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES BENZ	AMG GT 63	2019
MERCEDES BENZ	AMG GT 63 S	2019
MERCEDES BENZ	CLS450	2019
MERCEDES BENZ	CLS53	2019
MERCEDES BENZ	E300	2018-2019
MERCEDES BENZ	E400	2018
MERCEDES BENZ	E43 AMG	2018
MERCEDES BENZ	E450	2019
MERCEDES BENZ	E53	2019
MERCEDES BENZ	E63S AMG	2018-2019
MERCEDES BENZ	G550	2019
MERCEDES BENZ	G63	2019
MERCEDES BENZ	GLC300	2019
MERCEDES BENZ	GLC350E	2019
MERCEDES BENZ	GLC43 AMG	2019

**MAKE            MODEL            YEAR**

MERCEDES BENZ GLC63            2019  
MERCEDES BENZ GLC63 AMG   2019  
MERCEDES BENZ GLC63S AMG 2018-2019

## Side Curtain Air Bags May Be Damaged By Bolts

**NHTSA Campaign Number:** 19V802000

**Manufacturer** Hyundai Motor America

**Components** AIR BAGS

**Potential Number of Units Affected** 11,217

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2020 Palisade vehicles. The mounting bolts used to secure the side curtain air bags may damage the side curtain air bags during deployment.

### **Remedy**

Hyundai will notify owners, and dealers will install a protective cover on the mounting bolts, free of charge. The recall is expected to begin January 3, 2020. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 186.

### **Vehicle**

**MAKE    MODEL    YEAR**

HYUNDAI PALISADE 2020

## Passenger Frontal Air Bag Inflator May Explode

**NHTSA Campaign Number:** 19V782000

**Manufacturer** Mazda North American Operations

**Components** AIR BAGS

**Potential Number of Units Affected** 69,879

## Summary

Mazda North American Operations (Mazda) is recalling certain 2007-2012 CX-7, CX-9, and 2009-2012 Mazda6 vehicles. These vehicles had their passenger frontal air bag inflators previously replaced under a prior recall using inflators of the same design. The inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

## Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate one, free of charge. The recall is expected to begin December 18, 2019. Owners may contact Mazda customer service at 1-800-222-5500, option 4. Mazda's number for this recall is 1317F. Note: This recall supersedes recalls 16V356 and 17V012.

## Vehicles

### MAKE MODEL YEAR

MAZDA CX-7	2007-2012
MAZDA CX-9	2007-2012
MAZDA MAZDA6	2009-2012

## Passenger Frontal Air Bag Inflator May Explode

**NHTSA Campaign Number:** 19V781000

**Manufacturer** Mazda North American Operations

**Components** AIR BAGS

**Potential Number of Units Affected** 47,053

## Summary

Mazda North American Operations (Mazda) is recalling certain 2003-2008 Mazda6, 2004-2005 MPV, 2004 RX-8, and 2006-2007 Mazdaspeed6 vehicles. These vehicles had their passenger frontal air bag inflators previously replaced under a prior recall using inflators of the same design. The inflators may explode due to propellant degradation occurring after long-term exposure to high absolute humidity, temperature and temperature cycling.

## Remedy

Mazda will notify owners, and dealers will replace the front passenger air bag inflator with an alternate one, free of charge. The recall is expected to begin December 18, 2019. Owners may contact Mazda customer service at 1-800-222-5500, option 4. Mazda's number for this recall is 2618F. Note: This recall supersedes recalls 13V130, 14V362, 14V773 and 15V869.

## Vehicles

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MAZDA	MAZDA6	2003-2008
MAZDA	MAZDASPEED6	2006-2007
MAZDA	MPV	2004-2005
MAZDA	RX-8	2004

## Fuel Pump Relay May Fail Resulting In a Stall

**NHTSA Campaign Number:** 19V813000

**Manufacturer** Chrysler (FCA US LLC)

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 528,594

### Summary

Chrysler (FCA US LLC) is recalling certain 2011-2013 Dodge Durango and Jeep Grand Cherokee vehicles equipped with a 3.6, 5.7, or 6.4 liter engine and previously recalled under NHTSA Recall 14V530 or 15V115. The fuel pump relay inside the Totally Integrated Power Module (TIPM-7) may fail, causing the vehicle to stall without warning.

### Remedy

The remedy for this recall is still under development. Interim notices informing owners of the safety risk will be mailed beginning January 3, 2020. Vehicles that experience a fuel pump failure will receive an interim repair. Owners will receive a second notice when the final remedy becomes available. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is V62.

## Vehicles

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
DODGE	DURANGO	2011-2013
JEEP	GRAND CHEROKEE	2011-2013

## Inaccurate Vehicle Location for Emergency Services

**NHTSA Campaign Number:** 19V787000

**Manufacturer** Mercedes-Benz USA, LLC.

**Components** COMMUNICATION

**Potential Number of Units Affected** 24,226

### Summary

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2013-2017 vehicles due to a software fault that may cause the date and time for the emergency call system (eCall) to differ from the actual date and time, potentially relaying an inaccurate vehicle location. For a full list of the affected models visit:

<https://static.nhtsa.gov/odi/rcl/2019/RMISC-19V787-4620.pdf>

### Remedy

MBUSA has initiated an Over the Air (OTA) remote update. MBUSA will also notify owners, and dealers will check software for a successful OTA or update the communication module software as needed, free of charge. The recall is expected to begin December 31, 2019. Owners may contact MBUSA customer service at 1-800-367-6372.

### Vehicles

MAKE	MODEL	YEAR
MERCEDES BENZ	AMG GT	2017
MERCEDES BENZ	AMG GT S	2016-2017
MERCEDES BENZ	B-CLASS ELECTRIC	2014-2015
MERCEDES BENZ	B250E	2016
MERCEDES BENZ	C250	2013-2015
MERCEDES BENZ	C300	2013-2017
MERCEDES BENZ	C350	2013-2015
MERCEDES BENZ	C350E	2016
MERCEDES BENZ	C400	2015
MERCEDES BENZ	C450	2016
MERCEDES BENZ	C63 AMG	2013-2016
MERCEDES BENZ	C63S AMG	2015-2017
MERCEDES BENZ	CLS400	2015-2016
MERCEDES BENZ	CLS550	2013-2016
MERCEDES BENZ	CLS63	2013-2014
MERCEDES BENZ	CLS63S	2014-2016
MERCEDES BENZ	E250	2014-2016
MERCEDES BENZ	E350	2013

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES BENZ	E400	2015-2016
MERCEDES BENZ	E400 HYBRID	2013-2015
MERCEDES BENZ	E550	2013-2016
MERCEDES BENZ	E63	2013-2016
MERCEDES BENZ	E63S AMG	2013-2015
MERCEDES BENZ	G550	2013-2016
MERCEDES BENZ	G63	2013-2016
MERCEDES BENZ	G65	2016
MERCEDES BENZ	GL350	2013-2016
MERCEDES BENZ	GL450	2013-2016
MERCEDES BENZ	GL550	2013-2016
MERCEDES BENZ	GL63	2013-2016
MERCEDES BENZ	GLA250	2015-2016
MERCEDES BENZ	GLC300	2016
MERCEDES BENZ	GLE350	2016
MERCEDES BENZ	GLE400	2016
MERCEDES BENZ	GLE450	2016
MERCEDES BENZ	GLE550E	2016
MERCEDES BENZ	GLE63	2016
MERCEDES BENZ	GLE63S	2016
MERCEDES BENZ	GLK250	2013-2015
MERCEDES BENZ	GLK350	2013-2015
MERCEDES BENZ	GLS450	2017
MERCEDES BENZ	GLS550	2017
MERCEDES BENZ	GLS63	2017
MERCEDES BENZ	ML250	2015
MERCEDES BENZ	ML350	2013-2015
MERCEDES BENZ	ML400	2015
MERCEDES BENZ	ML550	2013-2014
MERCEDES BENZ	ML63	2013-2015
MERCEDES BENZ	S550	2014-2017
MERCEDES BENZ	S600	2015-2016
MERCEDES BENZ	S63	2014-2017
MERCEDES BENZ	S65 AMG	2015-2016
MERCEDES BENZ	SL400	2015-2016
MERCEDES BENZ	SL550	2013-2016
MERCEDES BENZ	SL63	2013-2015
MERCEDES BENZ	SL63 AMG	2016
MERCEDES BENZ	SL65	2013-2015
MERCEDES BENZ	SLK250	2013-2015



<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES BENZ	SLK300	2016
MERCEDES BENZ	SLK350	2013-2016
MERCEDES BENZ	SLK55	2014
MERCEDES BENZ	SLK55 AMG	2013, 2015-2016
MERCEDES-BENZ	CLA250	2014-2016
MERCEDES-BENZ	CLA45 AMG	2014-2016
MERCEDES-BENZ	E350	2014-2016
MERCEDES-BENZ	GLA45	2015-2016
MERCEDES-BENZ	GLE300D	2016
MERCEDES-BENZ	S550 4MATIC	2015-2016
MERCEDES-BENZ	S550 HYBRID	2015