



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

January 6, 2020

Emergency Braking Can Activate Unexpectedly

NHTSA Campaign Number: 19V907000

Manufacturer Mazda North American Operations

Components FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 35,390

Summary

Mazda North American Operations (Mazda) is recalling certain 2019-2020 Mazda3 vehicles. The Smart Brake System (SBS) can falsely detect an obstacle while driving, activating the automatic emergency braking system and suddenly stopping the vehicle.

Remedy

Mazda will notify owners, and dealers will update the SBS software. In addition, vehicles with certain production dates will receive an instrument cluster software update or replacement and a replacement owner's manual. These repairs will be performed free of charge. The recall is expected to begin February 17, 2020. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 4219L.

Vehicle

MAKE MODEL YEAR

MAZDA MAZDA3 2019-2020

Improperly Calibrated OCS

NHTSA Campaign Number: 19V892000

Manufacturer Mercedes-Benz USA, LLC.

Components AIR BAGS

Potential Number of Units Affected 129

Summary

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2015-2018 CLA250 and CLA250 4MATIC, and 2017-2018 CLA45 AMG vehicles. The Occupant Classification System (OCS) may have been improperly calibrated, which may prevent the proper deployment of the front passenger air bag.

Remedy

MBUSA will notify owners, and dealers will replace the passenger seat cushion, free of charge. The recall is expected to begin February 11, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	CLA250	2015-2018
MERCEDES-BENZ	CLA45 AMG	2017-2018

Fractured Right Rear Brake Caliper Can Fail

NHTSA Campaign Number: 19V909000

Manufacturer Chrysler (FCA US LLC)

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 1,352

Summary

Chrysler (FCA US LLC) is recalling certain 2020 Jeep Renegade and Fiat 500X vehicles. The right rear brake caliper could have been fractured during the casting process.

Remedy

Chrysler will notify owners, and dealers will inspect and replace the right rear brake calipers, as necessary, free of charge. The recall is expected to begin February 7, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is VE8.

Vehicles

MAKE MODEL YEAR

FIAT 500X 2020

JEEP RENEGADE 2020

Air Bag Control Module Incompatible With Air Bag

NHTSA Campaign Number: 19V910000

Manufacturer Subaru of America, Inc.

Components AIR BAGS

Potential Number of Units Affected 46

Summary

Subaru of America, Inc. (Subaru) is recalling certain 2016-2017 Outback vehicles. A replacement air bag control module may have been installed that is not compatible with the passenger air bag module, possibly affecting air bag deployment.

Remedy

Subaru will notify owners, and dealers will replace the passenger air bag module, free of charge. The recall is expected to begin February 14, 2020. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WUX-09.

Vehicle

MAKE MODEL YEAR

SUBARU OUTBACK 2016-2017

Rear Seat Belt Pretensioners May Not Lock

NHTSA Campaign Number: 19V912000

Manufacturer BMW of North America, LLC

Components SEAT BELTS

Potential Number of Units Affected 135

Summary

BMW of North America, LLC (BMW) is recalling certain 2019-2020 330i and 330i xDrive vehicles. The outboard rear seat belt pretensioners may not lock as intended during a crash.

Remedy

BMW will notify owners, and dealers will replace the rear seat belts, free of charge. The recall is expected to begin February 10, 2020. Owners may contact BMW customer at 1-800-525-7417.

Vehicle

MAKE MODEL YEAR

BMW 330I 2019-2020

Glass Panel May Detach From Vehicle

NHTSA Campaign Number: 19V918000

Manufacturer Mercedes-Benz USA, LLC.

Components VISIBILITY

Potential Number of Units Affected 744,852

Summary

Mercedes-Benz USA, LLC. (MBUSA) is recalling certain 2001-2011 vehicles. The bonding between the glass panel and the sliding roof frame may deteriorate, possibly resulting in the glass panel detaching from the vehicle. For a full list of the affected models visit: <https://static.nhtsa.gov/odi/rc1/2019/RMISC-19V918-4126.pdf>

Remedy

MBUSA will notify owners, and dealers will inspect the glass panel bonding and replace the sliding roof, as necessary, free of charge. The recall is expected to begin February 14, 2020. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE MODEL YEAR

MERCEDES BENZ	C230	2003-2007
MERCEDES BENZ	C240	2001-2005
MERCEDES BENZ	C280	2006-2007
MERCEDES BENZ	C32	2002-2004
MERCEDES BENZ	C320	2001-2005
MERCEDES BENZ	C350	2006-2007

MAKE	MODEL	YEAR
-------------	--------------	-------------

MERCEDES BENZ	C55	2005-2006
MERCEDES BENZ	CLK320	2003-2005
MERCEDES BENZ	CLK350	2006-2009
MERCEDES BENZ	CLK500	2003-2006
MERCEDES BENZ	CLK55	2003-2005
MERCEDES BENZ	CLK550	2007-2009
MERCEDES BENZ	CLS500	2006
MERCEDES BENZ	CLS55	2006
MERCEDES BENZ	CLS550	2007-2011
MERCEDES BENZ	CLS63	2007-2011
MERCEDES BENZ	E320	2003-2009
MERCEDES BENZ	E450	2006
MERCEDES BENZ	E500	2003-2006
MERCEDES BENZ	E55	2003-2006
MERCEDES BENZ	E550	2007-2009
MERCEDES BENZ	E63	2007-2009
MERCEDES-BENZ	E350	2006-2009