

# NHTSA Recalls of Interest March 16, 2020

## Brake Calipers Bolts May Break

NHTSA Campaign Number: 20V116000

Manufacturer General Motors LLC

**Components SERVICE BRAKES, HYDRAULIC** 

**Potential Number of Units Affected 20,352** 

#### **Summary**

General Motors LLC (GM) is recalling certain 2020 Chevrolet Silverado 1500 and GMC Sierra 1500 vehicles. The bolts used to attach the front and/or rear brake calipers may have not been heat treated and may break under load.

#### Remedy

GM will notify owners, and dealers will replace the brake caliper bolts, free of charge. The recall is expected to begin April 13, 2020. Owners may contact Chevrolet customer service at 1-800-222-1020 or GMC customer service at 1-866-522-9559. GM's number for this recall is N202294420.

#### **Vehicles**

MAKE MODEL YEAR

CHEVROLET SILVERADO 1500 2020

GMC SIERRA 1500 2020

## Replacement Blower Motor May Short

NHTSA Campaign Number: 20V137000

**Manufacturer** Ford Motor Company

**Components VISIBILITY** 

**Potential Number of Units Affected 5,384** 

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2019 Ranger vehicles previously repaired under recall 19V-726. The service replacement Heating, Ventilating and Air Conditioning (HVAC) blower motor that was installed may have an improper clearance between an electrical terminal and the conductive base plate that may result in an resistive electrical short.

#### Remedy

Ford will notify owners, and dealers will inspect and replace the HVAC blower motor, as necessary, free of charge. The recall is expected to begin April 6, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S12.

#### Vehicle

MAKE MODEL YEAR

FORD RANGER 2019

## Insufficient Fuel Tank Wall Thickness/Fuel Leak

NHTSA Campaign Number: 20V112000

Manufacturer Nissan North America. Inc.

Components FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected 46** 

#### **Summary**

Nissan North America, Inc. (Nissan) is recalling certain 2020 Versa vehicles. Due to a manufacturing issue, the fuel tank wall thickness may be insufficient, potentially causing a small hole in the tank seam area.

## Remedy

Nissan will notify owners, and dealers will replace the fuel tank, free of charge. The recall is expected to begin March 23, 2020. Owners may contact Nissan customer service at 1-800-867-7669.

### Vehicle

MAKE MODEL YEAR

NISSAN VERSA 2020