



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

April 20, 2020

Windshield Wipers May Not Operate Properly

NHTSA Campaign Number: 20V208000

Manufacturer Chrysler (FCA US LLC)

Components VISIBILITY

Potential Number of Units Affected 425,588

Summary

Chrysler (FCA US LLC) is recalling certain 2019-2020 Ram 1500, 1500 Classic and Jeep Compass vehicles. The windshield wiper arm or arms may loosen, possibly causing the wipers to not operate properly and reduce the driver's visibility in certain weather conditions.

Remedy

Chrysler will notify owners, and dealers will tighten the wiper nuts, free of charge. The recall is expected to begin May 29, 2020. Owners may contact Chrysler customer service at 1-800-853-1403. Chrysler's number for this recall is W25.

Vehicles

MAKE MODEL YEAR

JEEP COMPASS 2019-2020

RAM 1500 2019-2020

Possible Unintended Vehicle Movement

NHTSA Campaign Number: 20V213000

Manufacturer Hyundai Motor America

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 11,870

Summary

Hyundai Motor America (Hyundai) is recalling certain 2020 Nexo and Sonata vehicles. The Remote Smart Parking Assist (RSPA) software may fail to prevent vehicle movement upon detection of an RSPA system malfunction.

Remedy

Hyundai will notify owners, and dealers will reprogram the RSPA software, free of charge. The recall is expected to begin June 4, 2020. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 191.

Vehicles

MAKE MODEL YEAR

HYUNDAI NEXO 2020

HYUNDAI SONATA 2020

Back-Up Lights May Fail

NHTSA Campaign Number: 20V205000

Manufacturer Toyota Motor Engineering & Manufacturing

Components EXTERIOR LIGHTING

Potential Number of Units Affected 960

Summary

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2020 Corolla Hatchback vehicles. A rear hatch wire

harness connector may have been damaged during assembly, which may cause the back-up lights to fail.

Remedy

Toyota will notify owners, and dealers will replace the rear hatch wire harness, free of charge. The recall is expected to begin May 25, 2020. Owners may contact Toyota customer service at 1-888-270-9371. Toyota's numbers for this recall are 20TB07 and 20TA07.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

TOYOTA	COROLLA HATCHBACK	2020
--------	-------------------	------