



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

April 27, 2020

### Belt Tension Sensor Malfunction

**NHTSA Campaign Number:** 20V217000

**Manufacturer** Ford Motor Company

**Components** SEAT BELTS

**Potential Number of Units Affected** 1,355

#### **Summary**

Ford Motor Company (Ford) is recalling certain 2020 Expedition vehicles. The front passenger seatbelt buckle's Belt Tension Sensor (BTS) may malfunction and may result in the seat occupant being misclassified.

#### **Remedy**

Ford will notify owners, and dealers will replace the front passenger seatbelt buckle, free of charge. The recall is expected to begin May 11, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S17.

#### **Vehicle**

**MAKE MODEL YEAR**

FORD EXPEDITION 2020

## Fuel Pump May Become Inoperative/Engine Stall

**NHTSA Campaign Number:** 20V218000

**Manufacturer** Subaru of America, Inc.

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 188,207

### **Summary**

Subaru of America, Inc. (Subaru) is recalling certain 2019 Impreza, Outback, Legacy, and Ascent vehicles. The low pressure fuel pump may become inoperative.

### **Remedy**

Subaru will notify owners, and dealers will replace the low pressure fuel pump, free of charge. The recall is expected to begin June 5, 2020. Owners may contact Subaru customer service at 1-844-373-6614. Subaru's number for this recall is WRD-20.

### **Vehicles**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

SUBARU	ASCENT	2019
--------	--------	------

SUBARU	IMPREZA	2019
--------	---------	------

SUBARU	LEGACY	2019
--------	--------	------

SUBARU	OUTBACK	2019
--------	---------	------

## Seat Belts may not Restrain Occupant/FMVSS 209

**NHTSA Campaign Number:** 20V222000

**Manufacturer** TransitWorks

**Components** SEAT BELTS

**Potential Number of Units Affected** 241

### **Summary**

TransitWorks is recalling certain Driverge vehicles based on 2019-2020 Ford Transit vans equipped with Freedman Seating Company (FSC) PT Foldaway and GO-ES 3-point Foldaway seats. The seat belt retractor block out zone may have not been set correctly, potentially resulting in a seat belt that may not properly secure

the occupant. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 209, "Seat Belt Assemblies."

**Remedy**

TransitWorks will notify owners, and dealers will replace the retractors, free of charge. The manufacturer has not yet provided a notification schedule. Owners may contact TransitWorks customer service at 1-855-337-9543.

**Vehicle**

**MAKE MODEL YEAR**

FORD TRANSIT 2019-2020