



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

May 18, 2020

Pre-Collision Assist Can't be Enabled

NHTSA Campaign Number: 20V262000

Manufacturer Ford Motor Company

Components ELECTRICAL SYSTEM, FORWARD COLLISION AVOIDANCE

Potential Number of Units Affected 25,081

Summary

Ford Motor Company (Ford) is recalling certain 2020 Ford Expedition and Lincoln Navigator vehicles equipped with camera-only Pre-Collision Assist feature. Vehicles built with the optional radar-plus-camera Pre-Collision Assist system are not affected. Due to incorrect coding of interfacing modules, the Pre-Collision Assist feature is not enabled, and the driver cannot access the menu functions necessary to enable the Pre-Collision Assist feature.

Remedy

Ford will notify owners, and dealers will reprogram software for the Body Control Module, Antilock Braking System, Instrument Panel Cluster and Headlamp Control Modules, and reset the Tire Pressure Monitor System, free of charge. The recall is expected to begin May 25, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S20.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

FORD	EXPEDITION	2020
------	------------	------

LINCOLN	NAVIGATOR	2020
---------	-----------	------

Panoramic Roof Panel may Separate from Vehicle

NHTSA Campaign Number: 20V260000

Manufacturer Ford Motor Company

Components VISIBILITY

Potential Number of Units Affected 5,088

Summary

Ford Motor Company (Ford) is recalling certain model year 2014-2017 Transit Connect vehicles equipped with a Panoramic Fixed-Glass Vista roof. The panoramic roof panel may have been inadequately bonded to the vehicle, possibly resulting in the panel separating from the vehicle.

Remedy

Ford will notify owners, and dealers will remove, clean, and reinstall the panoramic roof panel, free of charge. The recall is expected to begin May 25, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S22.

Vehicle

MAKE	MODEL	YEAR
FORD	TRANSIT CONNECT	2014-2017

Loss of Electric Power Steering Assist

NHTSA Campaign Number: 20V254000

Manufacturer General Motors LLC

Components STEERING

Potential Number of Units Affected 1,826

Summary

General Motors LLC (GM) is recalling certain 2015-2016 Chevrolet Caprice Police Pursuit vehicles (PPV) and SS vehicles. Corrosion of the connector between the electric power steering module and the torque sensor connector may cause a loss of electric power steering assist.

Remedy

GM will notify owners, and dealers will replace the steering gear assembly, free of charge. The recall is expected to begin June 22, 2020. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N192285350.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	CAPRICE POLICE PURSUIT	2015-2016
CHEVROLET	SS	2015-2016

Possible Loss of Drive System and Power Steering

NHTSA Campaign Number: 20V251000

Manufacturer Daimler Trucks North America LLC

Components POWER TRAIN

Potential Number of Units Affected 5

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2019 Freightliner Business Class M2 trucks equipped with Cummins PowerDrive EV drivetrains, part numbers 4000EV, 6000EV, and 7000EV. A connector within the wire harness may become unplugged and cause loss of communication between control modules, resulting in sudden loss of drive power and power steering.

Remedy

Per Cummins, all of the affected vehicles have been remedied. Owners may contact DTNA customer service at 1-800-547-0712 or Cummins customer service at 1-800-286-6467. DTNA's number for this recall is FL-850.

Vehicle

MAKE	MODEL	YEAR
FREIGHTLINER	BUSINESS CLASS M2	2019

Automatic Traction Control May Malfunction

NHTSA Campaign Number: 20V256000, 20V257000

Manufacturer Autocar, LLC

Components TRACTION CONTROL SYSTEM

Potential Number of Units Affected 75

Summary

Autocar, LLC (Autocar) is recalling certain 2017-2021 Autocar Xpert vehicles equipped with Wabco Automatic Traction Control (ATC) electronic control units (ECU). The ATC ECUs may not be programmed correctly and may malfunction without warning.

Remedy

Autocar will notify owners, and dealers will reprogram the ATC ECU, free of charge. Owners may contact Autocar customer service at 1-888-218-3611 or 1-877-973-3486. The recall is expected to begin July 7, 2020. Autocar's number for this recall is ACMD-2001.

Vehicle

MAKE	MODEL	YEAR
AUTOCAR	XPERT	2017-2021
AUTOCAR	XPEDITOR	2016-2020