



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

June 22, 2020

### [Driveshaft Vibrations may cause Air bag Deployment](#)

**NHTSA Campaign Number:** 20V340000

**Manufacturer** Daimler Vans USA, LLC

**Components** POWER TRAIN, AIR BAGS

**Potential Number of Units Affected** 12

#### **Summary**

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019 Metris vans [platform 447 (VS20)] with gasoline engines and automatic transmissions. The driveshaft may not be attached to the intermediate bearing correctly, causing excessive wear to the driveshaft joint and excessive vibrations. This could be misinterpreted as acceleration or deceleration similar to a crash event and lead to an inadvertent deployment of the frontal airbags.

#### **Remedy**

DVUSA will notify owners and dealers will inspect the drive shaft, replacing it as necessary, free of charge. This recall is expected to begin July 24, 2020. Owners may contact DVUSA customer service at 1-877-762-8267. DVUSA's number for this recall is VS3DREIGE.

#### **Vehicle**

<b>MAKE</b>	<b>MODEL YEAR</b>
-------------	-------------------

MERCEDES BENZ	METRIS 2019
---------------	-------------

## Front Brake Caliper Bolts May Loosen and Fall Off

**NHTSA Campaign Number:** 20V346000

**Manufacturer** Mazda North American Operations

**Components** SERVICE BRAKES, HYDRAULIC

**Potential Number of Units Affected** 24,037

### **Summary**

Mazda North American Operations (Mazda) is recalling certain 2020 CX-30 and Mazda3 vehicles. The front brake caliper mounting bolts may not have been tightened properly during assembly, possibly allowing the calipers to loosen.

### **Remedy**

Mazda will notify owners, and dealers will inspect the front brake caliper bolts, tightening them as necessary. If bolts are missing, the affected brake caliper will be replaced. Repairs will be performed free of charge. This recall is expected to begin August 11, 2020. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 4420F.

### **Vehicles**

#### **MAKE MODEL YEAR**

MAZDA CX-30 2020

MAZDA MAZDA3 2020

## Disconnected Vent Hose May Cause Fuel Leak

**NHTSA Campaign Number:** 20V347000

**Manufacturer** Mazda North American Operations

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 12,097

### **Summary**

Mazda North American Operations (Mazda) is recalling certain 2020 CX-30 vehicles equipped with all-wheel drive. The evaporative vent hose for the fuel tank may be disconnected, possibly allowing fuel to leak from the charcoal canister vent at the rear of the vehicle.

## Remedy

Mazda will notify owners, and dealers will inspect the evaporative vent hose in the fuel tank. If the hose is disconnected, it will be reconnected and the charcoal canister with some related parts will be replaced. Repairs will be performed free of charge. This recall is expected to begin August 11, 2020. Owners may contact Mazda customer service at 1-800-222-5500, Option 4. Mazda's number for this recall is 4520F.

## Vehicle

### MAKE MODEL YEAR

MAZDA CX-30 2020

## Seat Belts May Not Restrain Occupant/FMVSS 209

**NHTSA Campaign Number:** 20V348000

**Manufacturer** Coach and Equipment Mfg Corp.

**Components** SEAT BELTS

**Potential Number of Units Affected** 72

## Summary

Coach and Equipment Mfg Corp. (Coach and Equipment) is recalling certain 2019-2020 Phoenix mini-buses built on Ford E Series Cutaway Chassis and equipped with Freedman Seating Company (FSC) PT Foldaway and GO-ES 3-point Foldaway seats. The seat belt retractor block out zone may have not been set correctly, potentially resulting in a seat belt that may not properly secure the occupant. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 209, "Seat Belt Assemblies."

## Remedy

Coach and Equipment will notify owners, and Freedman will replace the retractors, free of charge. The recall is expected to begin June 22, 2020. Dealers can contact Freedman Seating Company for parts and reimbursement information at 1-800-443-4540.

## Vehicle

**MAKE MODEL YEAR**

COACH AND EQUIPMENT PHOENIX 2019-2020