



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

August 24, 2020

Vehicle Exceeds Maximum Speed/FMVSS 500

NHTSA Campaign Number: 20V478000

Manufacturer Cruise Car, Inc.

Components VEHICLE SPEED CONTROL

Potential Number of Units Affected 27

Summary

Cruise Car, Inc. is recalling certain 2020 Moke low-speed vehicles. The vehicles may be able exceed the 40km/h maximum permissible speed to be classified as a low-speed vehicle. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 500, "Low Speed Vehicles."

Remedy

Cruise Car will notify owners, and dealers will calibrate the vehicle's maximum speed, free of charge. The recall is expected to begin September 1, 2020. Owners may contact Cruise Car customer service at 1-941-929-1630.

Vehicle

MAKE MODEL YEAR

CRUISE CAR MOKE 2020

Front Brake Calipers May Leak/FMVSS 122

NHTSA Campaign Number: 20V476000

Manufacturer BMW of North America, LLC

Components SERVICE BRAKES, HYDRAULIC, SERVICE BRAKES

Potential Number of Units Affected 9,392

Summary

BMW of North America, LLC (BMW) is recalling certain 2019-2020 R 1250 GS, GS Adventure and R 1250 RT, 2020 S 1000 RR and S 1000 XR motorcycles. The front brake calipers may leak brake fluid when parked. As such, these motorcycles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard number 122, "Motorcycle Brake Systems."

Remedy

BMW will notify owners, and dealers will inspect and if necessary, replace the front brake calipers with an improved version, free of charge. The recall is expected to begin October 6, 2020. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE	MODEL	YEAR
BMW	R 1250 GS	2019-2020
BMW	R 1250 GS ADVENTURE	2019-2020
BMW	R 1250 RT	2019-2020
BMW	S 1000 RR	2020
BMW	S 1000 XR	2020

Front Brake Hoses Could Rupture

NHTSA Campaign Number: 20V469000

Manufacturer Ford Motor Company

Components SERVICE BRAKES, HYDRAULIC, SERVICE BRAKES

Potential Number of Units Affected 488,594

Summary

Ford Motor Company (Ford) is recalling certain 2015-2018 Ford Edge and 2016-2018 Lincoln MKX vehicles. The front brake hoses may rupture prematurely.

Remedy

Ford will notify owners, and dealers will replace the front brake hoses with the new hoses that have a revised braid material, free of charge. Parts are not currently available. Ford will send an interim notification beginning September 14, 2020 to make owners aware of the issue. A second letter will be mailed once parts are available. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20S42.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

FORD	EDGE	2015-2018
------	------	-----------

LINCOLN	MKX	2016-2018
---------	-----	-----------