



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

Distorted or Inoperative Rearview Camera/FMVSS 111

NHTSA Campaign Number: 20V575000

Manufacturer Ford Motor Company

Components VISIBILITY

Potential Number of Units Affected 620,246

Summary

Ford Motor Company (Ford) is recalling certain 2020 Ford F-150, F-250, F-350, F-450, F-550, Explorer, Mustang, Transit, Expedition, Escape, Ranger and Edge, and Lincoln Nautilus and Corsair vehicles. Due to a poor electrical connection, the rearview camera may intermittently display a blank or distorted image. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

Ford will notify owners, and dealers will replace the rearview camera, free of charge. The recall is expected to begin November 7, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20C19.

Vehicles

MAKE	MODEL	YEAR
FORD	EDGE	2020
FORD	ESCAPE	2020

MAKE	MODEL	YEAR
FORD	EXPEDITION	2020
FORD	EXPLORER	2020
FORD	F-150	2020
FORD	F-250 SD	2020
FORD	F-350 SD	2020
FORD	F-450 SD	2020
FORD	F-550 SD	2020
FORD	MUSTANG	2020
FORD	RANGER	2020
FORD	TRANSIT	2020
LINCOLN	CORSAIR	2020
LINCOLN	NAUTILUS	2020

Tire Pressure Monitoring System Software/FMVSS 138

NHTSA Campaign Number: 20V585000

Manufacturer Jaguar Land Rover North America, LLC

Components TIRES, ELECTRICAL SYSTEM

Potential Number of Units Affected 11,950

Summary

Jaguar Land Rover North America, LLC (Land Rover) is recalling certain 2020-2021 Range Rover Sport vehicles equipped with 20-inch, 21-inch, or 22-inch wheels. The Tire Pressure Monitoring System (TPMS) recommended pressure has been set incorrectly in the instrument cluster. As a result, the TPMS warning light will not illuminate when tire pressure reaches 25% below the cold inflation pressure stated on the tire placard. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems."

Remedy

Land Rover will notify owners, and dealers will update the instrument cluster software, free of charge. The recall is expected to begin November 13, 2020. Owners may contact Land Rover customer service at 1-800-369-1000. Land Rover's number for this recall is N494.

Vehicle

MAKE	MODEL	YEAR
LAND ROVER	RANGE ROVER SPORT	2020-2021

Improperly Torqued Third Row Seat Belt Anchor Bolt

NHTSA Campaign Number: 20V579000

Manufacturer Volkswagen Group of America, Inc.

Components SEAT BELTS, Tether, Lower Anchor (on car seat or vehicle)

Potential Number of Units Affected 5

Summary

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2020 Tiguan LWB vehicles. The third row seat belt anchor bolts may not have been properly torqued.

Remedy

Volkswagen will notify owners and will repurchase the vehicles. Owners are advised: No one should occupy the third row seat due to the safety risk. The recall is expected to begin October 2, 2020. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen number for this recall is 69BA.

Vehicle

MAKE	MODEL YEAR
-------------	-------------------

VOLKSWAGEN	TIGUAN 2020
------------	-------------

Rear Window Glass May Separate

NHTSA Campaign Number: 20V570000

Manufacturer Nissan North America, Inc.

Components VISIBILITY

Potential Number of Units Affected 150

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2020 Altima, Maxima and Leaf vehicles. The rear window glass may not remain properly secured to the vehicle.

Remedy

Nissan will notify owners, and dealers will replace the back window glass, free of charge. The recall is expected to begin November 4, 2020. Owners may contact Nissan customer service at 1-800-867-7669. Nissan's number for this recall is PC752.

Vehicles

MAKE MODEL YEAR

NISSAN ALTIMA 2020

NISSAN LEAF 2020

NISSAN MAXIMA 2020

Brake Lights Stay Illuminated After Pedal Release

NHTSA Campaign Number: 20V567000

Manufacturer Daimler Trucks North America LLC

Components EXTERIOR LIGHTING

Potential Number of Units Affected 128,269

Summary

Daimler Trucks North America LLC (DTNA) is recalling certain 2017-2021 Cascadia P4 vehicles. The brake lights may remain illuminated after the brake pedal has been released.

Remedy

DTNA will notify owners, and dealers will replace the 3-pin brake pressure switch with a 2-pin brake pressure switch along with a jumper harness, free of charge. The recall is expected to begin November 16, 2020. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL-863.

Vehicle

MAKE MODEL YEAR

FREIGHTLINER CASCADIA 2017-2021