



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

March 2, 2020

### Front Passenger Seat Fasteners May Be Missing

**NHTSA Campaign Number:** 20V082000

**Manufacturer** Jaguar Land Rover North America, LLC

**Components** SEATS

**Potential Number of Units Affected** 1

#### **Summary**

Jaguar Land Rover North America, LLC (Jaguar) is recalling one 2020 I-Pace vehicle. The front passenger seat frame may be missing fasteners, resulting in a seat frame with insufficient strength.

#### **Remedy**

Jaguar will notify the owner, and a dealer will replace the front passenger seat assembly, free of charge. The recall is expected to begin April 9, 2020. Owners may contact Jaguar customer service at 1-800-452-4827. Jaguar's number for this recall is H282.

#### **Vehicle**

**MAKE MODEL YEAR**

JAGUAR I-PACE 2020

## Side Curtain Air bag May May Not Inflate Properly

**NHTSA Campaign Number:** 20V092000

**Manufacturer** Bentley Motors, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 4

### **Summary**

Bentley Motors, Inc. (Bentley) is recalling certain 2018-2020 Bentayga vehicles. In the event of a crash, the side curtain air bags may not properly inflate.

### **Remedy**

Bentley will notify owners, and dealers will replace the curtain air bags, free of charge. The recall is expected to begin March 17, 2020. Owners may contact Bentley customer service at 1-800-777-6923. Bentley's number for this recall is RE20/04.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

BENTLEY	BENTAYGA	2018-2020
---------	----------	-----------

## Side Curtain Air bags May Not Inflate Properly

**NHTSA Campaign Number:** 20V093000

**Manufacturer** Volkswagen Group of America, Inc.

**Components** AIR BAGS

**Potential Number of Units Affected** 383

### **Summary**

Volkswagen Group of America, Inc. (Volkswagen) is recalling certain 2019 Audi Q7 vehicles. In the event of a crash, the side curtain air bags may not properly inflate.

## **Remedy**

Volkswagen will notify owners, and dealers will replace the side curtain air bags, free of charge. The recall is expected to begin April 19, 2020. Owners may contact Volkswagen customer service at 1-800-893-5298. Volkswagen's number for this recall is 69AJ.

## **Vehicle**

### **MAKE MODEL YEAR**

AUDI Q7 2019

## **Daytime Running Lights May Not Dim/FMVSS 108**

**NHTSA Campaign Number:** 20V097000

**Manufacturer** Ford Motor Company

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 166,196

## **Summary**

Ford Motor Company (Ford) is recalling certain 2018-2020 F-150 trucks equipped with high series LED headlamps with Autolamp (On/Off) functionality. The Daytime Running Lamps (DRL) may remain activated instead of dimming to parking lamps when the Master Lighting Switch (MLS) is manually rotated from the "Autolamps" switch position to "Headlamps On." As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 108, "Lamps, Reflective Devices and Associated Equipment."

## **Remedy**

Ford will notify owners, and dealers will reprogram the body control module, free of charge. The recall is expected to begin March 9, 2020. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 20C03.

## **Vehicle**

### **MAKE MODEL YEAR**

FORD F-150 2018-2020