



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest January 25, 2021

Tire Tread Separation/Blowout

NHTSA Campaign Number: 21V007000

Manufacturer Daimler Trucks North America, LLC

Components TIRES

Potential Number of Units Affected 4,341

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2020-2022 Freightliner Cascadia sleeper trucks equipped with Bridgestone R284, R268, or R283S ECOPIA steer axle tires in conjunction with a specific air dam. The steer tires may experience tread separation or blow-outs while driving.

Remedy

DTNA will notify owners, and dealers will replace the steer tires, free of charge. The recall is expected to begin March 13, 2021. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL872.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

FREIGHTLINER	CASCADIA	2020-2022
--------------	----------	-----------

Brake Line Routing May Cause Wear and Fluid Leak

NHTSA Campaign Number: 21V008000

Manufacturer Braun Northwest

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 23

Summary

Braun Northwest (Braun Northwest) is recalling certain 2019-2020 RAM 4500/5500 vehicles equipped with Liquid Spring rear suspension systems. In the affected suspension systems, the rear brake caliper flexible line may have been routed so that it contacts a suspension component, possibly causing excessive wear and a loss of rear brakes.

Remedy

Braun Northwest will notify owners, and dealers will install a repair kit to each rear caliper and modify the rear brake caliper flexible line mounting. Any worn rear brake caliper flexible lines will be replaced as needed, free of charge. The manufacturer has not yet provided a schedule for recall notification. Owners may contact Braun Northwest customer service at 1-360-748-0195.

Vehicles

MAKE MODEL YEAR

RAM 4500 2019-2020

RAM 5500 2019-2020