



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest April 12, 2021

Second Row Center Seatbelt Latch Trapped/FMVSS 208

NHTSA Campaign Number: 21V210000

Manufacturer General Motors, LLC

Components SEAT BELTS

Potential Number of Units Affected 5

Summary

General Motors, LLC (GM) is recalling certain 2021 Chevrolet Tahoe vehicles. The second-row center seat belt latch may be trapped beneath the trim bezel and therefore inaccessible. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208. "Occupant Crash Protection."

Remedy

GM will notify owners, and dealers will remove the trim bezel, correctly position the seat belt latch plate, and reinstall the trim bezel, free of charge. The recall is expected to begin May 10, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N212329320.

Vehicle

MAKE MODEL YEAR

CHEVROLET TAHOE 2021

Seat Limiter may Allow Seat too Close to Air Bag

NHTSA Campaign Number: 21V216000

Manufacturer Mercedes-Benz USA, LLC

Components SEATS

Potential Number of Units Affected 109

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 E350, E450, E450 Wagon, E63S AMG, 2020 E63S AMG Wagon, and 2020-2021 E53 AMG vehicles. The passenger seat limiter may allow the seat to be positioned too close to the air bag.

Remedy

MBUSA will notify owners, and dealers will recalibrate the passenger seat limiter, free of charge. The recall is expected to begin May 25, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG E53	2020-2021
MERCEDES-BENZ	AMG E63S	2020-2021
MERCEDES-BENZ	E350	2021
MERCEDES-BENZ	E450	2021
MERCEDES-BENZ	E63 AMG	2020

Faulty Front Seat Position Switch

NHTSA Campaign Number: 21V230000

Manufacturer Mercedes-Benz USA, LLC

Components SEATS, AIR BAGS, SEAT BELTS

Potential Number of Units Affected 12,327

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 C-Class, E-Class, E-Class Coupe and Convertible, GLC, CLS, AMG GT 4-door Coupe and G-Class vehicles. Please refer to MBUSA's recall report

for specific vehicle model details. A faulty electrical contact within the seat position switch may prevent the driver and passenger air bags and seat belt force limiters from properly activating during a crash.

Remedy

MBUSA will notify owners, and dealers will replace the seat position switches, free of charge. The recall is expected to begin May 31, 2021. Owners may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG C43	2021
MERCEDES-BENZ	AMG C63	2021
MERCEDES-BENZ	AMG C63 S	2021
MERCEDES-BENZ	AMG CLS53	2021
MERCEDES-BENZ	AMG E53	2021
MERCEDES-BENZ	AMG G63	2021
MERCEDES-BENZ	AMG GLC43	2021
MERCEDES-BENZ	AMG GLC63	2021
MERCEDES-BENZ	AMG GLC63 S	2021
MERCEDES-BENZ	AMG GT43	2021
MERCEDES-BENZ	AMG GT53	2021
MERCEDES-BENZ	AMG GT63	2021
MERCEDES-BENZ	AMG GT63S	2021
MERCEDES-BENZ	C300	2021
MERCEDES-BENZ	CLS450	2021
MERCEDES-BENZ	E350	2021
MERCEDES-BENZ	E450	2021
MERCEDES-BENZ	G550	2021
MERCEDES-BENZ	GLC300	2021

Side Curtain Air Bag May Not Deploy

NHTSA Campaign Number: 21V221000

Manufacturer Chrysler (FCA US, LLC)

Components AIR BAGS

Potential Number of Units Affected 1,222

Summary

Chrysler (FCA US, LLC) is recalling certain 2021 Alfa Romeo Stelvio vehicles. An improperly crimped clamp may allow the side curtain air bag cushion and inflator to separate, causing an incomplete deployment or preventing the deployment of the air bag.

Remedy

Chrysler will notify owners, and dealers will replace the side air bag inflatable curtain assembly, free of charge. The recall is expected to begin May 19, 2021. Owners may contact FCA US LLC customer service at 1-800-853-1403. Chrysler's number for this recall is Y15.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

ALFA ROMEO	STELVIO	2021
------------	---------	------

Loss of Backup Camera Image/FMVSS 111

NHTSA Campaign Number: 21V223000

Manufacturer Ford Motor Company

Components BACK OVER PREVENTION

Potential Number of Units Affected 34,952

Summary

Ford Motor Company (Ford) is recalling certain 2020-2021 Lincoln Aviator vehicles. The image processing module may be unable to provide video feed to the display, which could result in a loss of the backup camera image. As such, these vehicles fail to comply with the requirements of the Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

Remedy

Ford will notify owners, and dealers will update the image processing module software with the latest level, free of charge. The recall is expected to begin May 19, 2021. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 21C09.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

LINCOLN	AVIATOR	2020-2021
---------	---------	-----------

Rearview Camera and Parking Sensors Malfunction

NHTSA Campaign Number: 21V228000

Manufacturer Mercedes-Benz USA, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 6

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2021 E350, E450, E450 Wagon, and AMG E63 vehicles. The parking control unit may fail to display the rearview camera image and cause the parking sensors to misidentify or fail to detect objects.

Remedy

All affected vehicles are still within MBUSA's control. MBUSA will replace the parking control unit, free of charge. The recall began April 8, 2021. Owner may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG E63	2021
MERCEDES-BENZ	E350	2021
MERCEDES-BENZ	E450	2021

Possible Loss of Steering Control

NHTSA Campaign Number: 21V229000

Manufacturer Mercedes-Benz USA, LLC

Components STEERING

Potential Number of Units Affected 4,992

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2017 B250e, CLA250, 2017-2018 AMG CLA45, GLA250, and AMG GLA45 vehicles. The steering shaft bore hole for the universal joint bearing may allow excessive movement that, over time, could result in the separation of the bearing and universal joint.

Remedy

MBUSA will notify owners, and dealers will inspect, and as necessary, replace the steering shaft, free of charge. The recall is expected to begin April 30, 2021. Owner may contact MBUSA customer service at 1-800-367-6372.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	AMG CLA45	2017-2018
MERCEDES-BENZ	AMG GLA45	2017-2018
MERCEDES-BENZ	B250E	2017
MERCEDES-BENZ	CLA250	2017
MERCEDES-BENZ	GLA250	2017-2018

Vehicle May Not Stay In Lane/FMVSS 136

NHTSA Campaign Number: 21V233000

Manufacturer Mack Trucks, Inc.

Components ELECTRONIC STABILITY CONTROL

Potential Number of Units Affected 566

Summary

Mack Trucks, Inc. (Mack) is recalling certain 2018-2022 Anthem (AN), Granite (GR/GU), and Pinnacle (CHU/CXU/PI) vehicles equipped with "camelback" rear suspension and electronic stability control. The vehicles may not stay in their lane at certain speeds. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 136, "Electronic Stability Control Systems on Heavy Vehicles."

Remedy

Mack will notify owners, and dealers will reprogram the vehicle control units, free of charge. The recall is expected to begin May 21, 2021. Owners may contact Mack customer service at 1-800-866-1177. Mack's number for this recall is SC0423.

Vehicles

MAKE	MODEL	YEAR
MACK	ANTHEM (AN)	2018-2022
MACK	GRANITE (GR)	2018-2022
MACK	GRANITE (GU)	2018-2022
MACK	PINNACLE (CHU)	2018-2022

MAKE	MODEL	YEAR
MACK	PINNACLE (CXU)	2018-2022
MACK	PINNACLE (PI)	2018-2022

Loss of Power Steering Assist

NHTSA Campaign Number: 21V213000

Manufacturer General Motors, LLC

Components STEERING

Potential Number of Units Affected 60,678

Summary

General Motors, LLC (GM) is recalling certain 2015 Chevrolet Colorado and GMC Canyon vehicles. The power steering assist may be lost due to a poor electrical connection within the steering gear assembly.

Remedy

GM will notify owners, and dealers will replace steering gear torque sensor cover assembly, free of charge. The recall is expected to begin May 10, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020, and GMC customer service at 1-800-462-8782. GM's number for this recall is N202325410.

Vehicles

MAKE	MODEL	YEAR
CHEVROLET	COLORADO	2015
GMC	CANYON	2015

Air Leak In Spring Brake Chamber

NHTSA Campaign Number: 21V226000

Manufacturer Navistar, Inc.

Components PARKING BRAKE

Potential Number of Units Affected 615

Summary

Navistar, Inc. (Navistar) is recalling certain 2021 International LT and International RH vehicles. The spring inside the spring brake chamber may allow the pressure plate to shift and wear a hole through the diaphragm.

Remedy

Navistar will notify owners, and dealers will inspect and, as necessary, replace the spring brake chambers, free of charge. The recall is expected to begin May 31, 2021. Owners may contact Navistar customer service at 1-800-448-7825. Navistar's number for this recall is 21502.

Vehicles

MAKE	MODEL YEAR
INTERNATIONAL LT	2021
INTERNATIONAL RH	2021

Engine Control Module May Cause Stall

NHTSA Campaign Number: 21V234000

Manufacturer Nissan North America, Inc.

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 12,943

Summary

Nissan North America, Inc. (INFINITI) is recalling certain 2021 INFINITI Q50 and Q60 vehicles. After detecting rapid acceleration, the Engine Control Module (ECM) may incorrectly reduce engine power and reduce fuel supply to the engine.

Remedy

INFINITI will notify owners, and dealers will reprogram the ECM software, free of charge. The recall is expected to begin May 25, 2021. Owners may contact INFINITI customer service at 1-800-662-6200. INFINITI's number for this recall is R20C5.

Vehicles

MAKE	MODEL YEAR
INFINITI Q50	2021
INFINITI Q60	2021

