



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest April 5, 2021

Steering Wheel Emblem May Separate

NHTSA Campaign Number: 21V211000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 30

Summary

General Motors, LLC (GM) is recalling certain 2017-2021 Chevrolet Camaro vehicles. The plastic "Camaro" emblem, located on the steering wheel air bag cover, may separate during deployment of the frontal driver air bag.

Remedy

GM will notify owners, and dealers will replace the frontal driver side air bag module, free of charge. The recall is expected to begin May 10, 2021. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N212327220.

Vehicle

MAKE MODEL YEAR

CHEVROLET CAMARO 2017-2021

Fuel Tank Weld may Fail and Allow Fuel Leak

NHTSA Campaign Number: 21V199000

Manufacturer BMW of North America, LLC

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 17

Summary

BMW of North America, LLC (BMW) is recalling certain 2021 X3 sDrive30i, X3 xDrive30i, X3 M40i, X3M, and X4, and 2021 X4 xDrive30i vehicles. The inlet check valve weld may fail, allowing the filling pipe to separate from the fuel tank.

Remedy

BMW will notify owners, and dealers will replace the fuel tank, free of charge. The recall is scheduled to begin May 17, 2021. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

BMW X3 2021

BMW X4 2021

Fuel Pump May Fail

NHTSA Campaign Number: 21V215000

Manufacturer Honda (American Honda Motor Co.)

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 628,124

Summary

Honda (American Honda Motor Co.) is recalling certain 2019-2020 Acura MDX, MDX Sport Hybrid, RDX, TLX, Honda Accord, Civic Hatchback, Insight, 2019 Acura ILX, Honda Accord Hybrid, Civic Coupe, Civic Coupe Si, Civic Sedan, Civic Sedan Si, Civic Type R, Fit, HR-V, Odyssey, Passport, Pilot and Ridgeline, and 2018-2019 CR-V vehicles. The low-pressure fuel pump inside the fuel tank may fail.

Remedy

Honda will notify owners, and dealers will replace the fuel pump assembly, free of charge. The recall is expected to begin May 18, 2021. Owners may contact Honda customer service at 1-888-234-2138. Note: This recall is an expansion of recall 20V-314.

Vehicles

MAKE	MODEL	YEAR
ACURA	ILX	2019
ACURA	MDX	2019-2020
ACURA	MDX SPORT HYBRID	2019-2020
ACURA	RDX	2019-2020
ACURA	TLX	2019-2020
HONDA	ACCORD	2019-2020
HONDA	ACCORD HYBRID	2019
HONDA	CIVIC	2019-2020
HONDA	CIVIC TYPE-R	2019
HONDA	CR-V	2018-2019
HONDA	FIT	2019
HONDA	HR-V	2019
HONDA	INSIGHT	2019-2020
HONDA	ODYSSEY	2019
HONDA	PASSPORT	2019
HONDA	PILOT	2019
HONDA	RIDGELINE	2019