

NHTSA Recalls of Interest May 24, 2021

Hydraulic Electronic Control Unit May Short

NHTSA Campaign Number: 21V331000

Manufacturer Kia Motors America

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 440,370

Summary

Kia Motors America (Kia) is recalling certain 2013-2015 Optima and 2014-2015 Sorento vehicles previously recalled under recall 20V-519. Brake fluid may leak inside the Hydraulic Electronic Control Unit (HECU), possibly resulting in an electrical short.

Remedy

Owners are advised to park outside and away from other vehicles and structures until the recall repair is completed.

Dealers will install a new multi-fuse, and inspect the HECU for leaks, replacing the HECU if necessary, free of charge. Owner notification letters are expected to be mailed July 2, 2021. This recall supersedes previous NHTSA recall number 20V-519. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC212.

Vehicles

MAKE MODEL YEAR

KIA OPTIMA 2013-2015 KIA SORENTO 2014-2015

Latch May Allow Rear Door To Open While Driving

NHTSA Campaign Number: 21V353000

Manufacturer Mercedes-Benz USA, LLC

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 17,800

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019-2021 G550 and G63 AMG vehicles. Components within the door latch may prevent the rear doors from latching or opening properly.

Remedy

Dealers will replace the rear door latches, free of charge. Owner notification letters are expected to be mailed July 13, 2021. Owners may contact MBUSA customer service at 1-800-367-6372. Note: Vehicles repaired prior to this recall must return to dealers to have remedy performed.

Vehicles

MAKE MODEL YEAR

MERCEDES-BENZ AMG G63 2019-2021 MERCEDES-BENZ G550 2019-2021

Supports In Roof Liner Insecurely Attached

NHTSA Campaign Number: 21V342000

Manufacturer BMW of North America, LLC

Components STRUCTURE

Potential Number of Units Affected 2

Summary

BMW of North America, LLC (BMW) is recalling certain 2021 BMW 230i and M240i vehicles. Supports within the roof liner may be insecurely attached.

Remedy

Dealers will inspect and repair or replace the roof liner as necessary, free of charge. Owner notification letters are expected to be mailed July 5, 2021. Owners may contact BMW customer service at 1-800-525-7417.

Vehicles

MAKE MODEL YEAR

BMW230I2021BMWM240I2021

Rearview Camera Image May Not Display/FMVSS 111

NHTSA Campaign Number: 21V354000

Manufacturer Mercedes-Benz USA, LLC

Components BACK OVER PREVENTION, ELECTRICAL SYSTEM

Potential Number of Units Affected 342,366

Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2019-2021 CLA-Class, GLE/GLS-Class, A-Class, E-Class, E-Class Coupe and Convertible, GLA/GLB-Class, GLC-Class, CLS-Class, and AMG GT-Class 4-door Coupe vehicles. Please refer to MBUSA's recall report for specific vehicle model details. The MBUX multimedia system software may cause the display to remain black, or reboot after startup. This could result in the rearview camera image not displaying properly. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard (FMVSS) number 111, "Rear Visibility."

Remedy

The multimedia system software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed July 13, 2021. Owners may contact MBUSA customer service at 1-800-367-6373.

Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ A2	20	2019-2021
MERCEDES-BENZ AM	1G A35	2020-2021
MERCEDES-BENZ AM	IG CLA35	2020-2021
MERCEDES-BENZ AM	IG CLA45	2020-2021
MERCEDES-BENZ AM	IG CLS53	2021
MERCEDES-BENZ AM	1G E53	2021
MERCEDES-BENZ AM	1G E63S	2021
MERCEDES-BENZ AM	IG GLA35	2021
MERCEDES-BENZ AM	IG GLA45	2021
MERCEDES-BENZ AM	IG GLB35	2021

MAKE	MODEL	YEAR
MERCEDES-BENZ A	MG GLC43	2020-2021
MERCEDES-BENZ A	MG GLC63	2020-2021
MERCEDES-BENZ A	MG GLE53	2021
MERCEDES-BENZ A	MG GLE63S	2021
MERCEDES-BENZ A	MG GLS63	2021
MERCEDES-BENZ A	MG GT43	2021
MERCEDES-BENZ A	MG GT53	2021
MERCEDES-BENZ A	MG GT63	2021
MERCEDES-BENZ A	MG GT63S	2021
MERCEDES-BENZ C	LA250	2020-2021
MERCEDES-BENZ C	LS450	2021
MERCEDES-BENZ E	350	2021
MERCEDES-BENZ E4	450	2021
MERCEDES-BENZ G	LA250	2021
MERCEDES-BENZ G	LB250	2020-2021
MERCEDES-BENZ G	LC300	2020-2021
MERCEDES-BENZ G	LC350E	2020
MERCEDES-BENZ G	LE350	2020-2021
MERCEDES-BENZ G	LE450	2020-2021
MERCEDES-BENZ G	LE580	2020-2021
MERCEDES-BENZ G	LS450	2020-2021
MERCEDES-BENZ G	LS580	2020-2021
MERCEDES-BENZ M	AYBACH GLS600	2021