



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest September 13, 2021

### Headlight Electrical Connector May Overheat

**NHTSA Campaign Number:** 21V688000

**Manufacturer** Toyota Motor Engineering & Manufacturing

**Components** ELECTRICAL SYSTEM, EXTERIOR LIGHTING

**Potential Number of Units Affected** 158,489

#### **Summary**

Toyota Motor Engineering & Manufacturing (Toyota) is recalling certain 2018-2021 Tundra vehicles. The headlight electrical circuits may power the high and low beams simultaneously, which could overheat the electrical connector.

#### **Remedy**

Dealers will modify the engine wire harness assembly and replace any damaged bulb, bulb connector, and/or headlight assembly as necessary, free of charge. Owner notification letters are expected to be mailed October 4, 2021. Owners may contact Toyota customer service at 1-800-331-4331. Toyota's numbers for this recall are 21TB06 and 21TA06.

#### **Vehicle**

**MAKE MODEL YEAR**

TOYOTA TUNDRA 2018-2021

