



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest January 24, 2022

Brake Light Malfunction and Possible Rollaway Risk

NHTSA Campaign Number: 22V011000

Manufacturer Ford Motor Company

Components SERVICE BRAKES, HYDRAULIC

Potential Number of Units Affected 199,085

Summary

Ford Motor Company (Ford) is recalling certain 2014-2015 Fusion, Lincoln MKZ, and 2015 Mustang vehicles originally sold or ever registered, in Texas, Louisiana, Mississippi, Alabama, Florida, Georgia, South Carolina, North Carolina, Virginia and Hawaii. Exposure to certain environmental conditions, such as high temperatures, high humidity, and salt air can cause the brake pedal bumper to corrode and separate from the brake pedal.

Remedy

Dealers will replace the brake pedal bumpers and clutch pedal bumpers, free of charge. Owner notification letters are expected to be mailed March 3, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S02.

Vehicles

MAKE	MODEL	YEAR
FORD	FUSION	2014-2015
FORD	MUSTANG	2015
LINCOLN	MKZ	2014-2015

Secondary Fuel Filter May Leak

NHTSA Campaign Number: 22V013000

Manufacturer Ford Motor Company

Components FUEL SYSTEM, DIESEL

Potential Number of Units Affected 19,697

Summary

Ford Motor Company (Ford) is recalling certain 2021 Super Duty F-250, F-350, F-450, F-550, F-600, and Medium Duty F-650 and F-750 vehicles equipped with 6.7L diesel engines. A small void may be present in the top-center of the vehicle's underhood secondary fuel filter cap, which may progress to a pinhole over time, allowing fuel to leak from the top of the secondary fuel filter.

Remedy

Dealers will replace the primary and secondary fuel filters, free of charge. Owner notification letters are expected to be mailed February 21, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S01.

Vehicles

MAKE MODEL YEAR

FORD F-250 SD 2021

FORD F-350 SD 2021

FORD F-450 SD 2021

FORD F-550 SD 2021

FORD F-600 SD 2021

FORD F-650 2021

FORD F-750 2021

Tire Belt Separation

NHTSA Campaign Number: 22V018000

Manufacturer Heartland Recreational Vehicles, LLC

Components TIRES

Potential Number of Units Affected 2,363

Summary

Heartland Recreational Vehicles, LLC (Heartland) is recalling certain 2021-2022 Cyclone, Fuel, Gravity, and Warrior vehicles equipped with certain Sailun tires, sizes ST235/80R16 and ST235/85R16. Due to a manufacturing issue, the tires may experience a belt separation.

Remedy

Dealers will inspect the tire DOT codes, and replace the tires as necessary, free of charge. Owner notification letters are expected to be mailed March 18, 2022. Owners may contact Heartland customer service at 1-877-262-8032 or Sailun customer service at 1-844-281-9696.

Vehicles

MAKE	MODEL	YEAR
HEARTLAND	CYCLONE	2021-2022
HEARTLAND	FUEL	2021-2022
HEARTLAND	GRAVITY	2021-2022
HEARTLAND	ROAD WARRIOR	2021-2022