



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest January 3, 2022

Front Trunk Hood May Open Unexpectedly/FMVSS 113

NHTSA Campaign Number: 21V00B000

Manufacturer Tesla, Inc.

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 119,009

Summary

Tesla, Inc. (Tesla) is recalling certain 2014-2021 Model S vehicles. The front trunk latch assembly may be misaligned, preventing the secondary hood latch from engaging. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 113, "Hood Latch System."

Remedy

Tesla Service will inspect and reposition the latch assembly as necessary, free of charge. Owner notification letters are expected to be mailed February 18, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-21-11-003.

Vehicle

MAKE MODEL YEAR

TESLA MODEL S 2014-2021

Rearview Camera Image May Not Display

NHTSA Campaign Number: 21V00D000

Manufacturer Tesla, Inc.

Components ELECTRICAL SYSTEM, VISIBILITY, BACK OVER PREVENTION

Potential Number of Units Affected 356,309

Summary

Tesla, Inc. (Tesla) is recalling all 2017-2020 Model 3 vehicles. The rearview camera cable harness may be damaged by the opening and closing of the trunk lid, preventing the rearview camera image from displaying.

Remedy

Tesla Service will inspect and install a guide protector and new cable harness as necessary, free of charge. Owner notification letters are expected to be mailed February 18, 2022. Owners may contact Tesla customer service at 1-877-798-3752. Tesla's number for this recall is SB-21-17-008.

Vehicle

MAKE MODEL YEAR

TESLA MODEL 3 2017-2020

GPS May Interfere with Brake or Throttle Pedals

NHTSA Campaign Number: 21V966000

Manufacturer Autocar, LLC

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 251

Summary

Autocar, LLC (Autocar) is recalling certain 2021-2022 Xpeditor vehicles. The GPS module may have been improperly mounted under the dashboard and could come loose or disconnect entirely.

Remedy

Dealers will remount the GPS module, free of charge. Owner notification letters are expected to be mailed February 10, 2022. Owners may contact Autocar customer service at 1-888-218-3611 or 1-877-973-3486. Autocar's number for this recall is ACX-2109.

Vehicle

MAKE MODEL YEAR

AUTOCAR XPEDITOR 2021-2022