



# Automotive Safety Council

Prevent Protect Notify

## NHTSA Recalls of Interest

May 31, 2022

### Disabled Emergency Call System

**NHTSA Campaign Number:** 22V365000

**Manufacturer** Mercedes-Benz USA, LLC

**Components** ELECTRICAL SYSTEM, COMMUNICATION

**Potential Number of Units Affected** 234,862

#### Summary

Mercedes-Benz USA, LLC (MBUSA) is recalling certain 2017-2022 CLA-Class, GLA-Class, GLE-Class, GLS-Class, SLC-Class, A-Class, AMG GT-Class, C-Class, E-Class, S-Class, SL-Class, GLC-Class, CLS-Class, GLB-Class, and G-Class vehicles. Please refer to MBUSA's recall report for specific vehicle model details. An error in the communication module's SIM card software can cause a mobile network connection failure, disabling the emergency call (eCall) system.

#### Remedy

The communication module software will be updated through an Over-the-Air (OTA) update or by a dealer, free of charge. Owner notification letters are expected to be mailed July 19, 2022. Owners may contact MBUSA customer service at 1-800-367-6372.

#### Vehicles

MAKE	MODEL	YEAR
MERCEDES-BENZ	A220	2019-2021

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
MERCEDES-BENZ	AMG A35	2020-2021
MERCEDES-BENZ	AMG C43	2019-2021
MERCEDES-BENZ	AMG C63	2019-2021
MERCEDES-BENZ	AMG CLA35	2020-2021
MERCEDES-BENZ	AMG CLA45	2019-2021
MERCEDES-BENZ	AMG CLS53	2019-2021
MERCEDES-BENZ	AMG E53	2019-2021
MERCEDES-BENZ	AMG E63	2019-2021
MERCEDES-BENZ	AMG G63	2019-2021
MERCEDES-BENZ	AMG GLA35	2021
MERCEDES-BENZ	AMG GLA45	2019-2021
MERCEDES-BENZ	AMG GLB35	2021
MERCEDES-BENZ	AMG GLC43	2019-2021
MERCEDES-BENZ	AMG GLC63	2019-2021
MERCEDES-BENZ	AMG GLE43	2019
MERCEDES-BENZ	AMG GLE53	2021-2022
MERCEDES-BENZ	AMG GLE63	2019-2021
MERCEDES-BENZ	AMG GLS63	2018-2021
MERCEDES-BENZ	AMG GT	2019-2021
MERCEDES-BENZ	AMG GT C	2019-2021
MERCEDES-BENZ	AMG GT R	2019-2020
MERCEDES-BENZ	AMG GT S	2019
MERCEDES-BENZ	AMG S63	2019-2021
MERCEDES-BENZ	AMG SL63	2019
MERCEDES-BENZ	AMG SLC43	2019-2020
MERCEDES-BENZ	C300	2017-2021
MERCEDES-BENZ	CLA250	2017-2021
MERCEDES-BENZ	CLS450	2019-2022
MERCEDES-BENZ	E300	2019
MERCEDES-BENZ	E350	2020-2021
MERCEDES-BENZ	E450	2019-2021
MERCEDES-BENZ	G550	2019-2021
MERCEDES-BENZ	GLA250	2017-2021
MERCEDES-BENZ	GLB250	2020-2021
MERCEDES-BENZ	GLC300	2018-2021
MERCEDES-BENZ	GLC350	2019-2020
MERCEDES-BENZ	GLE350	2018-2022
MERCEDES-BENZ	GLE400	2019
MERCEDES-BENZ	GLE450	2020-2022
MERCEDES-BENZ	GLE580	2020-2021
MERCEDES-BENZ	GLS450	2017-2022
MERCEDES-BENZ	GLS550	2019
MERCEDES-BENZ	GLS580	2020-2021

MAKE	MODEL	YEAR
MERCEDES-BENZ	GLS600	2021
MERCEDES-BENZ	S450	2019-2020
MERCEDES-BENZ	S500	2021
MERCEDES-BENZ	S560	2019-2020
MERCEDES-BENZ	S580	2021
MERCEDES-BENZ	S65 AMG	2019-2020
MERCEDES-BENZ	SL450	2019-2020
MERCEDES-BENZ	SL550	2019-2020
MERCEDES-BENZ	SLC300	2019-2020
MERCEDES-MAYBACH	S650	2019-2020

## Disabled Emergency Call System

**NHTSA Campaign Number:** 22V360000

**Manufacturer** Daimler Vans USA, LLC

**Components** ELECTRICAL SYSTEM, COMMUNICATION

**Potential Number of Units Affected** 19,937

### Summary

Daimler Vans USA, LLC (DVUSA) is recalling certain 2019-2021 Freightliner Sprinter, Mercedes-Benz Metris, and Mercedes-Benz Sprinter vehicles. An error in the communication module's SIM card software can cause a mobile network connection failure, disabling the emergency call (eCall) system.

### Remedy

The communication module software will be updated through an Over-the-Air (OTA) update, or by a dealer, free of charge. Owner notification letters are expected to be mailed June 20, 2022. Owners may contact DVUSA at 1-877-762-8267. DVUSA's number for this recall is VS2SIMKOM/VS3SIMKOM.

### Vehicles

MAKE	MODEL	YEAR
FREIGHTLINER	SPRINTER 1500	2019-2021
FREIGHTLINER	SPRINTER 2500	2019-2021
FREIGHTLINER	SPRINTER 3500	2019-2021
FREIGHTLINER	SPRINTER 4500	2019-2021
MERCEDES-BENZ	METRIS	2019-2021
MERCEDES-BENZ	SPRINTER 1500	2019-2021
MERCEDES-BENZ	SPRINTER 2500	2019-2021
MERCEDES-BENZ	SPRINTER 3500	2019-2021

**MAKE MODEL YEAR**

MERCEDES-BENZ SPRINTER 4500 2019-2021

## Missing Rear Impact Plate/FMVSS 223 & 224

**NHTSA Campaign Number:** 22V328000

**Manufacturer** Great Dane Trailers

**Components** EQUIPMENT

**Potential Number of Units Affected** 72

### **Summary**

Great Dane Trailers (Great Dane) is recalling certain 2019 Freedom Platform trailers. The platform trailers may have been produced without a rear impact guard (RIG) certification plate. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard numbers 223, "Rear Impact Guards", and 224, "Rear Impact Protection."

### **Remedy**

Dealers will provide new RIG certification plates stamped with the trailer date of manufacture, free of charge. Owner notification letters are expected to be mailed on June 8, 2022. Owners may contact Great Dane's customer service at 1-877-369-3493.

### **Vehicle**

**MAKE MODEL YEAR**

GREAT DANE FREEDOM 2019

## Inoperative Side Marker Lights/FMVSS 108

**NHTSA Campaign Number:** 22V326000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 15

### **Summary**

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Wrangler vehicles. The side marker lights may not function due to an incompatible tail light assembly wiring harness. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

## Remedy

FCA will replace the tail light assemblies, free of charge. Owner notification letters are expected to be mailed July 1, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z43.

## Vehicle

**MAKE MODEL YEAR**

JEEP WRANGLER 2022

## Hazard Lights May Flash While Braking/FMVSS 108

**NHTSA Campaign Number:** 22V327000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** EXTERIOR LIGHTING

**Potential Number of Units Affected** 20

### Summary

Chrysler (FCA US, LLC) is recalling certain 2022 Jeep Grand Cherokee and Grand Cherokee L vehicles. The vehicle's hazard lights may flash when the brake pedal is applied. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 108, "Lamps, Reflective Devices, and Associated Equipment."

## Remedy

Dealers will update the body control module, free of charge. Owner notification letters are expected to be mailed July 1, 2022. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is Z41.

## Vehicle

**MAKE MODEL YEAR**

JEEP GRAND CHEROKEE 2022

## Insufficient Welds in High Voltage Battery

**NHTSA Campaign Number:** 22V331000

**Manufacturer** Ford Motor Company

**Components** ELECTRICAL SYSTEM

## Potential Number of Units Affected 27

### Summary

Ford Motor Company (Ford) is recalling certain 2020 Escape and 2021 Lincoln Corsair vehicles equipped with 2.5L hybrid powertrains. Insufficient welds inside the high voltage battery may fail, resulting in a loss of drive power.

### Remedy

Dealers will replace the high voltage battery, free of charge. Owner notification letters are expected to be mailed July 5, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S33.

### Vehicles

#### MAKE MODEL YEAR

FORD ESCAPE 2020

LINCOLN CORSAIR 2021

## Disabled Display Screens/FMVSS 101

**NHTSA Campaign Number:** 22V351000

**Manufacturer** Lucid Motors, Inc.

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 1,117

### Summary

Lucid Motors, Inc. (Lucid) is recalling certain 2022 Air vehicles (all grades). The display wiring harness may not be secured properly, which can disable the display screens. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 101, "Control and Displays."

### Remedy

Dealers will inspect and secure the wiring harness, as necessary, free of charge. Owner notification letters are expected to be mailed June 20, 2022. Owners may contact Lucid customer service at 1-888-995-8243. Lucid's number for this recall is NCR-22-01-0.

### Vehicle

#### MAKE MODEL YEAR

LUCID AIR 2022

## Disabled Instrument Cluster Display Screen

**NHTSA Campaign Number:** 22V353000

**Manufacturer** Hyundai Motor America

**Components** ELECTRICAL SYSTEM

**Potential Number of Units Affected** 158

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2022 Palisade vehicles. The instrument cluster assembly may have been manufactured with excessive adhesive, which can disable the instrument cluster display screen.

### **Remedy**

Dealers will replace the instrument cluster assembly, free of charge. Owner notification letters are expected to be mailed July 15, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 230.

### **Vehicle**

<b>MAKE</b>	<b>MODEL</b>	<b>YEAR</b>
-------------	--------------	-------------

HYUNDAI	PALISADE	2022
---------	----------	------

## Seat Belt Pretensioners May Explode

**NHTSA Campaign Number:** 22V354000

**Manufacturer** Hyundai Motor America

**Components** SEAT BELTS

**Potential Number of Units Affected** 239,000

### **Summary**

Hyundai Motor America (Hyundai) is recalling certain 2019-2022 Accent, 2021-2023 Elantra, and 2021-2022 Elantra HEV vehicles. In the event of a crash, the front driver-side and/or passenger-side seat belt pretensioners may explode upon deployment.

### **Remedy**

Dealers will secure the seat belt pretensioner(s) with a cap, free of charge. Owner notification letters are expected to be mailed July 15, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 229. This recall expands and replaces NHTSA recall numbers 21V-796,

22V-069, 22V-218, and 22V-123 for Accent, Elantra, and Elantra HEV vehicles. All Accent, Elantra, and Elantra HEV vehicles already repaired under the previous recalls will need to have the new remedy completed.

## Vehicles

MAKE	MODEL	YEAR
HYUNDAI	ACCENT	2019-2022
HYUNDAI	ELANTRA	2021-2023
HYUNDAI	ELANTRA HEV	2021-2022

## Seat Cushion Frame Not Welded Properly

**NHTSA Campaign Number:** 22V359000

**Manufacturer** General Motors, LLC

**Components** SEATS

**Potential Number of Units Affected** 221

### Summary

General Motors, LLC (GM) is recalling certain 2021 Chevrolet Malibu, 2022 Chevrolet Equinox, Blazer and Cadillac XT4 vehicles. The driver's seat cushion frame may have an improper weld in the power tilt-adjustment mechanism.

### Remedy

Dealers will inspect the driver's seat and replace the cushion frame, as necessary, free of charge. Owner notification letters are expected to be mailed July 5, 2022. Owners may contact Chevrolet customer service at 1-800-222-1020 or Cadillac customer service at 1-800-458-8006. GM's number for this recall is N212356050.

## Vehicles

MAKE	MODEL	YEAR
CADILLAC	XT4	2022
CHEVROLET	BLAZER	2022
CHEVROLET	EQUINOX	2022
CHEVROLET	MALIBU	2021

