



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

June 13, 2022

Front Passenger Seat Frame Not Welded Properly

NHTSA Campaign Number: 22V375000

Manufacturer General Motors, LLC

Components SEATS

Potential Number of Units Affected 1,534

Summary

General Motors, LLC (GM) is recalling certain 2022 GMC Canyon and Chevrolet Colorado vehicles equipped with a manual passenger seat. The front passenger seat may have a hook attachment that was not properly welded, allowing it to separate from the inboard track of the seat frame.

Remedy

Dealers will inspect the front passenger seat and replace the cushion frame, if necessary, free of charge. Owner notification letters are expected to be mailed July 11, 2022. Owners may contact GMC customer service at 1-800-462-8782 or Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N222368320.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

CHEVROLET	COLORADO	2022
-----------	----------	------

GMC	CANYON	2022
-----	--------	------

Powertrain Control Module Malfunction

A rearview camera or reverse light that is disabled reduces the driver's rear view, increasing the risk of a crash. Disabled driver assist features (traction control, forward collision warning, blind spot warning, cross traffic indicator) may increase the risk of a crash.

NHTSA Campaign Number: 22V382000

Manufacturer Ford Motor Company

Components POWER TRAIN

Potential Number of Units Affected 25,032

Summary

Ford Motor Company (Ford) is recalling certain 2019-2020 Mustang vehicles equipped with 5.0L engines and manual transmissions. The Powertrain Control Module (PCM) may broadcast an unintended faulted signal to the modules controlling the reverse camera, reverse light, and driver assist features, which may disable all of these functions.

Remedy

Dealers will update the PCM software, free of charge. Owner notification letters are expected to be mailed June 13, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22S37.

Vehicle

MAKE MODEL YEAR

FORD MUSTANG 2019-2020

Steering Gear Assembled Incorrectly

NHTSA Campaign Number: 22V399000

Manufacturer Volvo Trucks North America

Components STEERING

Potential Number of Units Affected 1,632

Summary

Volvo Trucks North America (Volvo Trucks) is recalling certain 2022-2023 VN tractor trailers. The steering gears may have been assembled incorrectly, which can cause the gear to fracture.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed July 29, 2022. Owners may contact Volvo Truck customer service at 1-800-528-6586. Volvo Truck's number for this recall is RVXX2202.

Vehicle

MAKE MODEL YEAR

VOLVO VN 2022-2023

Steering Gear Incorrectly Assembled

NHTSA Campaign Number: 22V405000

Manufacturer Daimler Trucks North America, LLC

Components STEERING

Potential Number of Units Affected 6,492

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2021-2022 Freightliner (FCCC) MT45, 2022-2023 Western Star 4900 and Freightliner Cascadia vehicles. The steering gears may have been incorrectly assembled, which can cause the gear to fracture.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed August 6, 2022. Owners may contact DTNA's customer service at 1-800-547-0712. DTNA's number for this recall is FL-938.

Vehicles

MAKE MODEL YEAR

FCCC	MT45	2021-2022
FREIGHTLINER	CASCADIA	2022-2023
WESTERN STAR	4900	2022-2023