



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

June 6, 2022

Engine Control Unit Short-Circuit May Cause Stall

NHTSA Campaign Number: 22V368000

Manufacturer Volkswagen Group of America, Inc.

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 72

Summary

Volkswagen Group of America, Inc. (Audi) is recalling certain 2022 Audi A6 Sedan, A4 Sedan, Q5, and Q5 Sportback vehicles. The semiconductor inside the engine control unit may short-circuit and cause an engine stall.

Remedy

Dealers will replace the engine control unit, free of charge. Owner notification letters are expected to be mailed July 22, 2022. Owners may contact Audi customer service at 1-800-253-2834. Audi's number for this recall is 24iH.

Vehicles

MAKE MODEL YEAR

AUDI	A4	2022
AUDI	A6	2022
AUDI	Q5	2022

Double Check Valve May Trap Air and Impair Braking

NHTSA Campaign Number: 22V374000

Manufacturer Daimler Trucks North America, LLC

Components SERVICE BRAKES, AIR

Potential Number of Units Affected 4

Summary

Daimler Trucks North America LLC (DTNA) is recalling certain 2022 Freightliner Cascadia vehicles. The double check valve may trap air which can impair service brake function and lock the rear axle while the vehicle is in motion. A locked rear axle may cause brake components to fail or increased stopping distance.

Remedy

Dealers will remove the double check valve, free of charge. Owner notification letters are expected to be mailed July 23, 2022. Owners may contact DTNA customer service at 1-800-547-2712. DTNA's number for this recall is FL-936.

Vehicle

MAKE	MODEL	YEAR
-------------	--------------	-------------

FREIGHTLINER	CASCADIA	2022
--------------	----------	------

Incorrect Tire Pressure Monitoring Information

NHTSA Campaign Number: 22V379000

Manufacturer Daimler Trucks North America, LLC

Components TIRES

Potential Number of Units Affected 2,549

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2017-2022 FCCC XC Chassis vehicles. The tire pressure monitoring system (TPMS) may report incorrect information, such as temperature and pressure values, on the instrument cluster.

Remedy

Dealers will update the TPMS software, free of charge. Owner notification letters are expected to be mailed July 25, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL935.

Vehicle

MAKE MODEL YEAR

FCCC XC CHASSIS 2017-2022

Inaccurate Fuel Gauge Reading

NHTSA Campaign Number: 22V380000

Manufacturer Honda (American Honda Motor Co.)

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 212

Summary

Honda (American Honda Motor Co.) is recalling certain 2020 CR-V vehicles. The clip for the absorber inside the fuel tank was not secured properly and may detach, which can cause an inaccurate fuel gauge reading.

Remedy

Dealers will replace the fuel tank, free of charge. Owner notification letters are expected to be mailed July 5, 2022. Owners may contact Honda customer service at 1-888-234-2138. Honda's number for this recall is RCB.

Vehicle

MAKE MODEL YEAR

HONDA CR-V 2020