



Automotive Safety Council

Prevent

Protect

Notify

NHTSA Recalls of Interest

July 4, 2022

Seat Belt Pretensioners May Explode

NHTSA Campaign Number: 22V458000

Manufacturer Hyundai Motor America

Components SEAT BELTS

Potential Number of Units Affected 72,470

Summary

Hyundai Motor America (Hyundai) is recalling certain 2020-2022 Venue vehicles. In the event of a crash, the front driver-side and/or passenger-side seat belt pretensioners may explode upon deployment.

Remedy

Dealers will secure the seat belt pretensioners with a cap, free of charge. Owner notification letters are expected to be mailed August 26, 2022. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 231. This recall expands and replaces NHTSA recall number 21V-796 for Venue vehicles. Venue vehicles previously repaired under 21V-796 will need to have the new remedy completed.

Vehicle

MAKE MODEL YEAR

HYUNDAI VENUE 2020-2022

Seat Belt Pretensioners May Explode

NHTSA Campaign Number: 22V447000

Manufacturer Kia Motors America

Components SEAT BELTS

Potential Number of Units Affected 17,199

Summary

Kia Motors America (Kia) is recalling certain 2021-2022 Sorento Hybrid and 2022 Sorento Plug-in Hybrid vehicles. In the event of a crash, the front driver-side and/or passenger-side seat belt pretensioner(s) may explode upon deployment.

Remedy

Dealers will secure the seat belt pretensioners with a cap, free of charge. Owner notification letters are expected to be mailed August 19, 2022. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC241. This recall expands and replaces NHTSA recall number 22V-127. Vehicles already repaired under the previous recall will need to have the new remedy completed.

Vehicles

MAKE	MODEL	YEAR
KIA	SORENTO HYBRID	2021-2022
KIA	SORENTO PHEV	2022

Emergency Braking System May Not Engage

NHTSA Campaign Number: 22V443000

Manufacturer Daimler Trucks North America, LLC

Components SERVICE BRAKES

Potential Number of Units Affected 17

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2022 Freightliner Cascadia vehicles. The emergency braking system may not engage, resulting in the loss of braking ability.

Remedy

Dealers will install a double check valve, free of charge. Owner notification letters are expected to be mailed August 21, 2022. Owners may contact DNTA customer service at 1-800-547-0712. DTNA's number for this recall is FL-941.

Vehicle

MAKE MODEL YEAR

FREIGHTLINER CASCADIA 2022

Malfunctioning Hood Latch

NHTSA Campaign Number: 22V420000

Manufacturer Nissan North America, Inc.

Components LATCHES/LOCKS/LINKAGES

Potential Number of Units Affected 322,671

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2013-2016 Pathfinder vehicles. On certain Pathfinder vehicles, the secondary hood latch may malfunction and remain in the unlatched, unsecured, position when the hood is closed.

Remedy

The remedy is in development. Owner notification letters are expected to be mailed July 18, 2020. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall are R22A2 and R22A3.

Vehicle

MAKE MODEL YEAR

NISSAN PATHFINDER 2013-2016

Unexpected Engine Shut Down

NHTSA Campaign Number: 22V438000

Manufacturer Daimler Trucks North America, LLC

Components ENGINE AND ENGINE COOLING

Potential Number of Units Affected 468

Summary

Daimler Trucks North America, LLC (DTNA) is recalling certain 2020-2023 Thomas Built C2 Saf-T-Liner school buses equipped with 8.8L LPG engines. The engine control module (ECM) may set a fault code that results in an unexpected engine shut down.

Remedy

The remedy is currently under development. Owner notification letters are expected to be mailed August 19, 2022. Owners may contact DTNA customer service at 1-800-547-0712. DTNA's number for this recall is FL942.

Vehicle

MAKE	MODEL	YEAR
------	-------	------

THOMAS BUILT BUSES SAF-T-LINER C2	2020-2023	
-----------------------------------	-----------	--

Fuel Tank Rollover Valve May Not Properly Seal

NHTSA Campaign Number: 22V446000

Manufacturer General Motors, LLC

Components FUEL SYSTEM, GASOLINE

Potential Number of Units Affected 228

Summary

General Motors, LLC (GM) is recalling certain 2022 Cadillac XT5, XT6, and GMC Acadia All-Wheel Drive (AWD) vehicles. The fuel tank rollover valve may not provide a proper seal in the event of a rollover crash.

Remedy

Dealers will inspect the fuel tank and replace the fuel tank shell if the rollover valve is found to be dislodged or missing, free of charge. Owner notification letters are expected to be mailed August 8, 2022. Owners may contact Cadillac customer service at 1-800-458-8006 and GMC customer service at 1-800-462-8782. GM's number for this recall is N222366070.

Vehicles

MAKE	MODEL	YEAR
------	-------	------

CADILLAC	XT5	2022
CADILLAC	XT6	2022
GMC	ACADIA	2022

TPMS Light May Not Illuminate/FMVSS 138

NHTSA Campaign Number: 22V453000

Manufacturer Ford Motor Company

Components TIRES

Potential Number of Units Affected 2,666

Summary

Ford Motor Company (Ford) is recalling certain 2022 F-150 BEV vehicles equipped with 20" or 22" all season tires. The tire pressure monitoring system (TPMS) light may not illuminate as intended, failing to warn the driver of low tire pressure. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 138, "Tire Pressure Monitoring Systems."

Remedy

The body control module (BCM) software will be updated by a dealer, or through an over-the-air (OTA) update, free of charge. Owner notification letters are expected to be mailed July 11, 2022. Owners may contact Ford customer service at 1-866-436-7332. Ford's number for this recall is 22C15.

Vehicle

MAKE MODEL YEAR

FORD F-150 BEV 2022

Unsecured Transmission May Cause Rollaway

NHTSA Campaign Number: 22V457000

Manufacturer Nissan North America, Inc.

Components POWER TRAIN

Potential Number of Units Affected 180,176

Summary

Nissan North America, Inc. (Nissan) is recalling certain 2020-2022 Frontier and Titan vehicles. The transmission parking pawl may not engage when the vehicle is shifted into park, which can result in a vehicle rollaway.

Remedy

Owners are advised to apply the parking brake every time they park their vehicle. The remedy is currently under development. Interim owner notification letters are expected to be mailed July 20, 2022. Second letters will be mailed once the remedy is available. Owners may contact Nissan's customer service at 1-800-867-7669. Nissan's number for this recall is R22A2 R22A3.

Vehicles

MAKE	MODEL	YEAR
-------------	--------------	-------------

NISSAN	FRONTIER	2020-2022
--------	----------	-----------

NISSAN	TITAN	2020-2022
--------	-------	-----------