



Automotive Safety Council

Prevent Protect Notify

NHTSA Recalls of Interest

December 12, 2022

Rearview Camera May Fail

Failure of the rearview camera image to display can reduce the driver's rear visibility, increasing the risk of a crash.

NHTSA Campaign Number: 22V868000

Manufacturer General Motors, LLC

Components BACK OVER PREVENTION

Potential Number of Units Affected 10,194

Summary

General Motors, LLC (GM) is recalling certain 2019-2020 Cadillac XT4 vehicles equipped with the optional Surround Vision feature. The video processing module (VPM) may lose communication with the rearview camera, causing a loss of the rearview camera image.

Remedy

Dealers will update the VPM software or replace the VPM, as necessary, free of charge. Owner notification letters are expected to be mailed January 9, 2023. Owners may contact Cadillac customer service at 1-800-458-8006. GM's number for this recall is N222373320.

.Vehicle

MAKE	MODEL	YEAR
CADILLAC	XT4	2019-2020

Air Bags May Not Deploy in a Crash/FMVSS 208

An SDM in manufacturing mode will not deploy the vehicle's air bags in a crash, increasing the risk of occupant injury.

NHTSA Campaign Number: 22V873000

Manufacturer General Motors, LLC

Components AIR BAGS

Potential Number of Units Affected 5

Summary

General Motors, LLC (GM) is recalling certain 2022 Chevrolet Silverado 1500 vehicles. The sensing diagnostic module (SDM) was left in manufacturing mode and not activated at the assembly plant prior to shipment. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 208, "Occupant Crash Protection."

Remedy

Dealers returned the vehicles to the GM assembly plant and the sensing diagnostic modules were activated. The vehicles had not been sold from dealer inventory and therefore no owner letters will be mailed. Owners may contact Chevrolet customer service at 1-800-222-1020. GM's number for this recall is N222387870.

Vehicle

MAKE	MODEL	YEAR
CHEVROLET	SILVERADO 1500	2022

Air Bag May Deploy Improperly

An improper air bag deployment increases the risk of injury in a crash.

NHTSA Campaign Number: 22V897000

Manufacturer Porsche Cars North America, Inc.

Components STRUCTURE, AIR BAGS

Potential Number of Units Affected 53

Summary

Porsche Cars North America, Inc. (Porsche) is recalling certain 2022-2023 911 vehicles. In the event of a crash with passenger air bag deployment, the dashboard console may break, causing the air bag to deploy improperly.

Remedy

Dealers will replace the dashboard, free of charge. Owner notification letters are expected to be mailed February 3, 2023. Owners may contact Porsche's customer service at 1-800-767-7243. Porsche's number for this recall is ANB7.

Vehicle

MAKE	MODEL	YEAR
PORSCHE	911	2022-2023

Coolant Leak in EPCU may Cause Loss of Drive Power

Coolant contacting the EPCU circuit board may cause a loss of drive power, increasing the risk of a crash.

NHTSA Campaign Number: 22V899000

Manufacturer Kia America, Inc.

Components ELECTRICAL SYSTEM

Potential Number of Units Affected 872

Summary

Kia America, Inc. (Kia) is recalling certain 2020 Niro EV vehicles. The Electric Power Control Unit (EPCU) may have been improperly sealed and may leak coolant internally.

Remedy

Dealers will inspect and replace the EPCU as necessary, free of charge. Owner notification letters are expected to be mailed January 31, 2023. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC258.

Vehicle

MAKE	MODEL	YEAR
KIA	NIRO EV	2020
