



# Automotive Safety Council

Prevent

Protect

Notify

## NHTSA Recalls of Interest

September 25, 2023

### Rearview Camera Image May Not Display/FMVSS 111

A rearview camera that does not display an image can reduce the driver's rear view, increasing the risk of a crash.

**NHTSA Campaign Number:** 23V639000

**Manufacturer** Kia America, Inc.

**Components** BACK OVER PREVENTION

**Potential Number of Units Affected** 83,667

#### Summary

Kia America, Inc. (Kia) is recalling certain 2019 Sorento vehicles. Due to a manufacturing error, water may leak into the rearview camera, which can cause the rearview camera image not to appear on the display. As such, these vehicles fail to comply with the requirements of Federal Motor Vehicle Safety Standard number 111, "Rear Visibility."

#### Remedy

Dealers will inspect the rearview camera and add additional water proofing to the camera harness, or replace the camera as necessary, free of charge. Owner notification letters are expected to be mailed November 13, 2023. Owners may contact Kia customer service at 1-800-333-4542. Kia's number for this recall is SC282.

#### Vehicle

---

MAKE	MODEL	YEAR
KIA	SORENTO	2019

---

## Loss of Drive Power from Fuel Pump Failure

A loss of drive power can increase the risk of a crash.

**NHTSA Campaign Number:** 23V630000

**Manufacturer** Hyundai Motor America

**Components** FUEL SYSTEM, GASOLINE

**Potential Number of Units Affected** 19,272

### Summary

Hyundai Motor America (Hyundai) is recalling certain 2021-2022 Genesis G80, GV80, and 2022 Genesis GV70 vehicles. The fuel pump may fail, which can result in a loss of drive power.

### Remedy

Dealers will replace the fuel pump, free of charge. Owner notification letters are expected to be mailed November 10, 2023. Owners may contact Hyundai customer service at 1-855-371-9460. Hyundai's number for this recall is 016G.

### Vehicles

MAKE	MODEL	YEAR
GENESIS	G80	2021-2022
GENESIS	GV70	2022
GENESIS	GV80	2021-2022

## Shifter May Come Out of Gear While Driving

A sudden loss of drive power can increase the risk of a crash.

**NHTSA Campaign Number:** 23V640000

**Manufacturer** Chrysler (FCA US, LLC)

**Components** POWER TRAIN

**Potential Number of Units Affected** 125

**Summary** Chrysler (FCA US, LLC) is recalling certain 2023 Dodge Durango Pursuit vehicles equipped with an instrument panel mounted shifter. The shifter may experience an interference with the shifter boot and come out of gear while driving, which can result in a sudden loss of drive power.

## Remedy

Dealers will replace the instrument panel mounted shifter boot, free of charge. Owner notification letters are expected to be mailed November 7, 2023. Owners may contact FCA US, LLC customer service at 1-800-853-1403. FCA US, LLC's number for this recall is 94A.

## Vehicle

---

MAKE	MODEL	YEAR
DODGE	DURANGO	2023

---